



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name /Ting Kay Chong Reg No/Reg Date SLP7848Z / 19/06/201 Date In/Mileage 23/11/2020/ 0 Chassis No JMYSRCY1AGU006783 Engine No 4A92CP4458 Make/Model MIT/16MY LANCER EX 1.6 4AT (E21) Colour/Trim DOO LIGHTNING BLUE / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	23/11/2020/ 12:19	QUK	282 / Kevin Leong	59871
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
E PNT88000	REPLACE FRT BUMPER, FRT BOTH FENDER, BONNET, SUPPORT & AFFECTED AREA	450	✓	1800.	3600.00
E PNT98000	REPAIR ON BOTH FRONT BODY CHASSIS, & FRT LH DOOR	350	✓	1750.	2450.00
E PNT88000	PAINT WORK ON FRT BUMPER, BONNET, BOTH FRT FENDER, BOTH FRT BODY CHASSIS & FRT LH DOOR				120.00
E PNT88000	TO REMOVE & INSTALL RADIATOR, CONDENSER FOR FACILITATE REPAIR				80.00
M SUNDRY	TO TOP UP AIRCON GAS				450.00
A 11900199	TO REPLACE ENGINE COMPONENTS				80.00
M SUNDRY	PERFORM RUST PREVENTION				30.00
A 54900099	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				120.00
A 10028901	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				50.00
M SUNDRY	TO SUPPLY FRONT NUMBER PLATE WITH FRAME				50.00
M SUNDRY	SUNDRIES				
M HEADLAMP ASSY,LH		1.00	846.00	23.00	651.42
M HEADLAMP ASSY,RH		1.00	846.00	23.00	651.42
M LAMP ASSY,SIDE MARKER,RH		1.00	607.00	23.00	467.39
M LAMP ASSY,FOG,FR LH		1.00	303.00	23.00	233.31
M HORN		1.00	89.00	23.00	68.53
M REINFORCEMENT,FR BUMPER		1.00	93.00	23.00	71.61
M FACE,FR BUMPER		1.00	1040.00	23.00	800.80
M REINFORCEMENT,FR BUMPER		1.00	529.00	23.00	407.33
M GRILLE,RADIATOR		1.00	268.00	23.00	206.36
M GRILLE,FR BUMPER		1.00	78.00	23.00	60.06

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 1977014696

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name /Ting Kay Chong Reg No/Reg Date SLP7848Z / 19/06/201 Date In/Mileage 23/11/2020/ 0 Chassis No JMYSRCY1AGU006783 Engine No 4A92CP4458 Make/Model MIT/16MY LANCER EX 1.6 4AT (E21) Colour/Trim D00 LIGHTNING BLUE / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	23/11/2020/ 12:19	QUK	282 / Kevin Leong	59871

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M GARNISH,FR BUMPER,CTR	1.00	234.00	23.00	180.18
M COVER,HEADLAMP SUPT PANEL	1.00	70.00	23.00	53.90
M SUPPORT,FR BUMPER,RH	1.00	13.00	23.00	10.01
M SUPPORT,FR BUMPER,LH	1.00	13.00	23.00	10.01
M BRACKET,FR BUMPER SIDE,LH	1.00	17.00	23.00	13.09
M BRACKET,FR BUMPER SIDE,RH	1.00	17.00	23.00	13.09
M MARK,THREE-DIA	1.00	69.00	23.00	53.13
M COVER,FR BUMPER	1.00	38.00	23.00	29.26
M HOOD	1.00	913.00	23.00	703.01
M WEATHERSTRIP,HOOD	1.00	18.00	23.00	13.86
M WEATHERSTRIP,HOOD,FR	1.00	31.00	23.00	23.87
M HINGE,HOOD,LH	1.00	64.00	23.00	49.28
M HINGE,HOOD,RH	1.00	64.00	23.00	49.28
M LATCH,HOOD	1.00	58.00	23.00	44.66
M FENDER,FR RH	1.00	688.00	23.00	529.76
M FENDER,FR LH	1.00	688.00	23.00	529.76
M PNL,HEADLAMP SUPT,UPR RH	1.00	86.00	23.00	66.22
M EXTENSION,FR SIDEMEMBER,RH	1.00	41.00	23.00	31.57
M PANEL,HEADLAMP SUPPORT,UPR	1.00	296.00	23.00	227.92
M SHIELD,FR FENDER,FR RH	1.00	119.00	23.00	91.63
M GARNISH,FR DECK	1.00	137.00	23.00	105.49
M BRACKET,ROLL STOPPER	1.00	121.00	23.00	93.17
M BRACKET,ENG FR MOUNTING	1.00	194.00	23.00	149.38

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SURVEYOR NAME: Tan Kah 17495747SURVEYOR SIGNATURE: [Signature]DATE: 23/11/20REMARKS: Not Authorise Ex: theRunning by the paint.
Tan Kah 17495747 8 days

Confirm & accepted by

7% GST on Net
13719.76 13,719.76
960.38
Total Payable 14,680.14

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.