



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI
MOTORS

ESTIMATE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name /Rajagopal Vedharathnam Reg No/Reg Date SMA2383Y / 31/05/201 Date In/Mileage / 29111 Chassis No MMBSTA13AJH001684 Engine No 3A92UGR8640 Make/Model MIT/18MY ATTRAGE 1.2 CVT Colour/Trim A06 COOL SILVER MET/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	23/11/2020/ 14:40	QUD	247 / DonBong	59876
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW ACCIDENT DAMAGED PARTS ON REAR BOOT LID, REAR BUMPER CUT/WELD REAR END PANEL, LH REAR FENDER, REPAIR RH REAR FENDER, REPAIR REAR FLOOR PANEL		2700	3150.00		
E PNT88000 REMOVE AND INSTALL REAR CABIN TO FACILITATE REPAIR WORK			120.00		
E PNT88000 REMOVE AND INSTALL PARKING SENSOR			60.00		
E PNT88000 REMOVE AND INSTALL REAR WINDSCREEN GLASS			240.00		
M SUNDRY SUPPLY REAR WINDSCREEN SEALANT			80.00		
E PNT98000 PAINT WORK SPRAY REAR FLOOR PANEL, REAR END PANEL, REAR BOOT LID, REAR BUMPER FACE, RH REAR FENDER, LH REAR FENDER, REAR BODY KITS, REAR SPOILER AND AFFECTED PORTION		2625	3150.00		
M SUNDRY SUPPLY PARKING SENSOR		X 9	220.00		
M SUNDRY SUPPLY C&C LOGO			40.00		
A 54900099 CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM			30.00		
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST			120.00		
M SUNDRY RE-APPLY ZERTONA COATING ON AFFECTED PORTION		80	320.00		
M SUNDRY APPLY BODY SEALANT			120.00		
M SUNDRY PERFORM RUST PREVENTION		80	120.00		
M SUNDRY SUPPLY REAR NUMBER PLATE WITH FRAME			50.00		

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name /Rajagopal Vedharathnam Reg No/Reg Date SMA2383Y / 31/05/201 Date In/Mileage / 29111 Chassis No MMBSTA13AJH001684 Engine No 3A92UGR8640 Make/Model MIT/18MY ATTRAGE 1.2 CVT Colour/Trim A06 COOL SILVER MET/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	23/11/2020/ 14:40	QUD	247 / DonBong	59876			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M SUNDRY								20 50.00
SUNDRIES								
M	PANEL,RR END	4/			1.00	425.00	23.00	327.25
M	TRIM,RR END	de/			1.00	66.00	23.00	50.82
M	GROMMET,RR END TRIM	re/			2.00	3.00	23.00	4.62
M	BOARD,TRUNK ROOM FLOOR	cm/			1.00	195.00	23.00	150.15
M	HINGE,TRUNK LID,LH	? X			1.00	203.00	23.00	156.31
M	HINGE,TRUNK LID,RH	? X			1.00	203.00	23.00	156.31
M	WEATHERSTRIP,TRUNK LID	? X			1.00	157.00	23.00	120.89
M	LATCH,TRUNK LID	? X			1.00	218.00	23.00	167.86
M	STRIKER,TRUNK LID LATCH	? X			1.00	20.00	23.00	15.40
M	PANEL,TRUNK LID	bus/			1.00	791.00	23.00	609.07
M	CHROME GARNISH,RR END PANEL	? ✓			1.00	336.00	23.00	258.72
M	MARK,THREE-DIA	re/			1.00	69.00	23.00	53.13
M	MARK,ATTRAGE	re/			1.00	21.00	23.00	16.17
M	DUCT,RR VENTILATOR	cut/			1.00	30.00	23.00	23.10
M	COVER,RR VENTILATOR	? ✓			1.00	40.00	23.00	30.80
M	CLIP,GEARSHIFT CONTROL LIN	? ✓			3.00	3.00	23.00	6.93
M	ANT,KEYLESS OPERATION,RR	? ✓			1.00	96.00	23.00	73.92
M	BUZZER,KEYLESS OPERATIO,RR	? ✓			1.00	91.00	23.00	70.07
M	LAMP ASSY,COMB,RR LH	? X			1.00	335.00	23.00	257.95
M	LAMP ASSY,COMB,RR RH	cm/			1.00	335.00	23.00	257.95
M	GROMMET,TAIL LAMP	re/			2.00	3.00	23.00	4.62
M	GROMMET,TAIL LAMP	re/			4.00	3.00	23.00	9.24
M	PANEL,QTR,OTR RH	bus/			1.00	763.00	23.00	587.51
M	PANEL,RR COMB LAMP HSG,RH	? X			1.00	60.00	23.00	46.20
M	EXTN,QTR PANEL,UPR OTR RH	? X			1.00	118.00	23.00	90.86
M	STOPPER,WINDSHIELD GLASS	re/			2.00	3.00	23.00	4.62
M	SPACER,RR WINDOW	re/			3.00	9.00	23.00	20.79
M	BRACKET,RR BUMPER,LH	? X			1.00	28.00	23.00	21.56
M	BRACKET,RR BUMPER,RH	? X			1.00	28.00	23.00	21.56
M	CLIP,RR BUMPER	re/			4.00	4.00	23.00	12.32
M	FACE,RR BUMPER	de/			1.00	748.00	23.00	575.96

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI
MOTORS

ESTIMATE

Co Reg No : 1977014696

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name /Rajagopal Vedharathnam Reg No/Reg Date SMA2383Y / 31/05/201 Date In/Mileage / 29111 Chassis No MMBSTA13AJH001684 Engine No 3A92UGR8640 Make/Model MIT/18MY ATTRAGE 1.2 CVT Colour/Trim A06 COOL SILVER MET/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	23/11/2020/ 14:40	QUD	247 / DonBong	59876

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M ATTRAGE BODYKITS <i>cm</i>	1.00	1643.00	00.00	1643.00
M DECAL, MIVEC <i>new</i> <i>X</i>	1.00	36.00	23.00	27.72

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Estimate

SURVEYOR NAME: *Rasul - 48 90010068*SURVEYOR SIGNATURE: *[Signature]*DATE: *23/11/2020 2/610*REMARKS: *12 days**EXCESS: TBA / REVERS**Resurvey before print*

Confirm & accepted by

13,782.65

7% GST on 13743.38


Nett 13,743.38
962.04

Total Payable

14,705.42

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

INSURANCE CO. : AIG

Supplementary For Registration No.: SMA 2383 Y

<u>Materials</u>		<u>Cost \$</u>
1	Lamp Assy, License Plate	51.00 ✓
	23% Discount	11.73
		39.27
	7% GST	2.75
	Total	42.02

Thank You.

Yours faithfully
CYCLE & CARRIAGE AUTOMOTIVE PTE LTD

Larry Songcuan
Customer Service
Cycle & Carriage
Pandan Gardens
Tel. # 6568 4658