



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	<table> <tr> <td>Cust No/Name</td><td>/Rajagopal Vedharathnam</td></tr> <tr> <td>Reg No/Reg Date</td><td>SMA2383Y / 31/05/201</td></tr> <tr> <td>Date In/Mileage</td><td>/ 29111</td></tr> <tr> <td>Chassis No</td><td>MMBSTA13AJH001684</td></tr> <tr> <td>Engine No</td><td>3A92UGR8640</td></tr> <tr> <td>Make/Model</td><td>MIT/18MY ATTRAGE 1.2 CVT</td></tr> <tr> <td>Colour/Trim</td><td>A06 COOL SILVER MET/ BK BLACK</td></tr> </table>	Cust No/Name	/Rajagopal Vedharathnam	Reg No/Reg Date	SMA2383Y / 31/05/201	Date In/Mileage	/ 29111	Chassis No	MMBSTA13AJH001684	Engine No	3A92UGR8640	Make/Model	MIT/18MY ATTRAGE 1.2 CVT	Colour/Trim	A06 COOL SILVER MET/ BK BLACK
Cust No/Name	/Rajagopal Vedharathnam														
Reg No/Reg Date	SMA2383Y / 31/05/201														
Date In/Mileage	/ 29111														
Chassis No	MMBSTA13AJH001684														
Engine No	3A92UGR8640														
Make/Model	MIT/18MY ATTRAGE 1.2 CVT														
Colour/Trim	A06 COOL SILVER MET/ BK BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	23/11/2020/ 14:40	QUD	247 / DonBong	59876
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
E PNT88000	RENEW ACCIDENT DAMAGED PARTS ON REAR BOOT LID, REAR BUMPER, CUT/WELD REAR END PANEL, LH REAR FENDER, REPAIR RH REAR FENDER, REPAIR REAR FLOOR PANEL	450 x 6	2700		3150.00
E PNT88000	REMOVE AND INSTALL REAR CABIN TO FACILITATE REPAIR WORK				120.00
E PNT88000	REMOVE AND INSTALL PARKING SENSOR				60.00
E PNT88000	REMOVE AND INSTALL REAR WINDSCREEN GLASS				240.00
M SUNDRY	SUPPLY REAR WINDSCREEN SEALANT				80.00
E PNT98000	PAINT WORK SPRAY REAR FLOOR PANEL, REAR END PANEL, REAR BOOT LID, REAR BUMPER FACE, RH REAR FENDER, LH REAR FENDER, REAR BODY KITS, REAR SPOILER AND AFFECTED PORTION	@350 x 7.5	2625		3150.00
M SUNDRY	SUPPLY PARKING SENSOR				220.00
M SUNDRY	SUPPLY C&C LOGO				40.00
A 54900099	CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM				30.00
A 10028901	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				120.00
M SUNDRY	RE-APPLY ZERTONA COATING ON AFFECTED PORTION	@80 x 4			320.00
M SUNDRY	APPLY BODY SEALANT				120.00
M SUNDRY	PERFORM RUST PREVENTION				80
M SUNDRY	SUPPLY REAR NUMBER PLATE WITH FRAME	LA			50.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 1977014696

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	<table> <tr> <td>Cust No/Name</td><td>/Rajagopal Vedharathnam</td></tr> <tr> <td>Reg No/Reg Date</td><td>SMA2383Y / 31/05/201</td></tr> <tr> <td>Date In/Mileage</td><td>/ 29111</td></tr> <tr> <td>Chassis No</td><td>MMBSTA13AJH001684</td></tr> <tr> <td>Engine No</td><td>3A92UGR8640</td></tr> <tr> <td>Make/Model</td><td>MIT/18MY ATTRAGE 1.2 CVT</td></tr> <tr> <td>Colour/Trim</td><td>A06 COOL SILVER MET/ BK BLACK</td></tr> </table>	Cust No/Name	/Rajagopal Vedharathnam	Reg No/Reg Date	SMA2383Y / 31/05/201	Date In/Mileage	/ 29111	Chassis No	MMBSTA13AJH001684	Engine No	3A92UGR8640	Make/Model	MIT/18MY ATTRAGE 1.2 CVT	Colour/Trim	A06 COOL SILVER MET/ BK BLACK
Cust No/Name	/Rajagopal Vedharathnam														
Reg No/Reg Date	SMA2383Y / 31/05/201														
Date In/Mileage	/ 29111														
Chassis No	MMBSTA13AJH001684														
Engine No	3A92UGR8640														
Make/Model	MIT/18MY ATTRAGE 1.2 CVT														
Colour/Trim	A06 COOL SILVER MET/ BK BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	23/11/2020/ 14:40	QUD	247 / DonBong	59876
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M SUNDRY					
SUNDRIES					20 50.00
M PANEL,RR END <i>ly</i>		1.00	425.00	23.00	327.25
M TRIM,RR END <i>de</i>		1.00	66.00	23.00	50.82
M GROMMET,RR END TRIM <i>ren</i>		2.00	3.00	23.00	4.62
M BOARD,TRUNK ROOM FLOOR <i>cm</i>		1.00	195.00	23.00	150.15
M HINGE,TRUNK LID,LH <i>? xsvl</i>		1.00	203.00	23.00	156.31
M HINGE,TRUNK LID,RH <i>? xsvl</i>		1.00	203.00	23.00	156.31
M WEATHERSTRIP,TRUNK LID <i>? xsvl</i>		1.00	157.00	23.00	120.89
M LATCH,TRUNK LID <i>? xsvl</i>		1.00	218.00	23.00	167.86
M STRIKER,TRUNK LID LATCH <i>? xsvl</i>		1.00	20.00	23.00	15.40
M PANEL,TRUNK LID <i>bu</i>		1.00	791.00	23.00	609.07
M CHROME GARNISH,RR END PANEL <i>? cm</i>		1.00	336.00	23.00	258.72
M MARK,THREE-DIA <i>ren</i>		1.00	69.00	23.00	53.13
M MARK,ATTRAGE <i>ren</i>		1.00	21.00	23.00	16.17
M DUCT,RR VENTILATOR <i>? cut</i>		1.00	30.00	23.00	23.10
M COVER,RR VENTILATOR <i>? cut</i>		1.00	40.00	23.00	30.80
M CLIP,GEARSHIFT CONTROL LIN <i>? ren</i>	X NN	3.00	3.00	23.00	6.93
M ANT,KEYLESS OPERATION,RR <i>? cm</i>	X SVC	1.00	96.00	23.00	73.92
M BUZZER,KEYLESS OPERATIO,RR <i>? cm</i>		1.00	91.00	23.00	70.07
M LAMP ASSY,COMB,RR LH <i>? xsvl</i>		1.00	335.00	23.00	257.95
M LAMP ASSY,COMB,RR RH <i>cm</i>		1.00	335.00	23.00	257.95
M GROMMET,TAIL LAMP <i>ren</i>		2.00	3.00	23.00	4.62
M GROMMET,TAIL LAMP <i>ren</i>		4.00	3.00	23.00	9.24
M PANEL,QTR,OTR RH <i>bu</i>		1.00	763.00	23.00	587.51
M PANEL,RR COMB LAMP HSG,RH <i>? xsvl</i>		1.00	60.00	23.00	46.20
M EXTN,QTR PANEL,UPR OTR RH <i>? xsvl</i>		1.00	118.00	23.00	90.86
M STOPPER,WINDSHIELD GLASS <i>ren</i>		2.00	3.00	23.00	4.62
M SPACER,RR WINDOW <i>ren</i>		3.00	9.00	23.00	20.79
M BRACKET,RR BUMPER,LH <i>? xsvl</i>		1.00	28.00	23.00	21.56
M BRACKET,RR BUMPER,RH <i>? xsvl</i>		1.00	28.00	23.00	21.56
M CLIP,RR BUMPER <i>ren</i>		4.00	4.00	23.00	12.32
M FACE,RR BUMPER <i>de</i>		1.00	748.00	23.00	575.96

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI
MOTORS

Co Reg No : 1977014696

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	<table> <tr> <td>Cust No/Name</td><td>/Rajagopal Vedharathnam</td></tr> <tr> <td>Reg No/Reg Date</td><td>SMA2383Y / 31/05/201</td></tr> <tr> <td>Date In/Mileage</td><td>/ 29111</td></tr> <tr> <td>Chassis No</td><td>MMBSTA13AJH001684</td></tr> <tr> <td>Engine No</td><td>3A92UGR8640</td></tr> <tr> <td>Make/Model</td><td>MIT/18MY ATTRAGE 1.2 CVT</td></tr> <tr> <td>Colour/Trim</td><td>A06 COOL SILVER MET/ BK BLACK</td></tr> </table>	Cust No/Name	/Rajagopal Vedharathnam	Reg No/Reg Date	SMA2383Y / 31/05/201	Date In/Mileage	/ 29111	Chassis No	MMBSTA13AJH001684	Engine No	3A92UGR8640	Make/Model	MIT/18MY ATTRAGE 1.2 CVT	Colour/Trim	A06 COOL SILVER MET/ BK BLACK
Cust No/Name	/Rajagopal Vedharathnam														
Reg No/Reg Date	SMA2383Y / 31/05/201														
Date In/Mileage	/ 29111														
Chassis No	MMBSTA13AJH001684														
Engine No	3A92UGR8640														
Make/Model	MIT/18MY ATTRAGE 1.2 CVT														
Colour/Trim	A06 COOL SILVER MET/ BK BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	23/11/2020/ 14:40	QUD	247 / DonBong	59876

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M ATTRAGE BODYKITS CM ✓	1.00	1643.00	00.00	1643.00
M DECAL, MIVEC Acc X NM	1.00	36.00	23.00	27.72

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SURVEYOR NAME: Rasul - 4p 20010068SURVEYOR SIGNATURE: [Signature]DATE: 23/11/2020 @ 1610REMARKS: 12 daysEXCESS: TBA / REVERSReem before print

Confirm & accepted by


13,782.65

7% GST on	13743.38	962.04
-----------	----------	--------

Total Payable 14,705.42

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

INSURANCE CO. : AIG

Supplementary For Registration No.: SMA 2383 Y

<u>Materials</u>		<u>Cost \$</u>
1	Lamp Assy, License Plate cra ✓	51.00 ✓
	23% Discount	11.73
		<hr/> 39.27
	7% GST	2.75
	Total	<hr/> 42.02

Thank You.

Yours faithfully
CYCLE & CARRIAGE AUTOMOTIVE PTE LTD

Larry Songcuan
Customer Service
Cycle & Carriage
Pandan Gardens
Tel. # 6568 4658