

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle Number : SMS 6689U

Date : 20.11.2020

Vehicle Model : SUBARU FORESTER CVT

Chassis : JF1SK7KL5KG018923

Accident Date : 19.11.2020

TP

FIRST CAP

Original Reg Date : 09.03.2020

ESTIMATE

1	1 pc	Tailgate Badge		NN	del	82.50
2	1 pc	Tailgate Emblem (Subaru)			del	72.00
3	1 pc	Tailgate Emblem (AXA)			del	68.00
4	1 pc	Tailgate Emblem (Forester)			del	72.00
5	1 pc	Tailgate Emblem (GT)			del	68.00
6	1 pc	Tailgate Emblem (Eyesight)			del	72.00
7	1 pc	Tailgate Weatherstrip			del	192.20
8	1 pc	Rear Bumper			del	690.20
9	1 pc	Rear Bumper Tow Cover			mis	29.00
10	2 pcs	Rear Bumper Side Retainers	photo LH-del	39.00	RHX	78.00
11	2 pcs	Rear Bumper Attachment Retainers	photo LH-del	42.00	RHX	84.00
12	1 set	Rear Bumper Clips			300g	40.00
13	1 pc	Rear Bumper Reinforcement			bt	295.00
14	2 pcs	Rear Bumper Reflexor	LH-RV	(95.00)	RHX	190.00
15	1 pc	Rear Bumper Lower Skirt			cut	386.20
16	1 pc	Rear Bumper Lower Spoiler		880	cut	1,280.00
17	1 pc	End Panel			bt	521.50
18	1 pc	End Panel Top Trim			del	126.20
19	1 set	End Panel Top Trim Clips			del	30.00
20	1 pc	Spare Tyre Panel			Ry	792.50
21	1 pc	Spare Tyre Panel Top Sponge			CX	369.50
22	1 pc	Spare Tyre Wheel Nut	photo		bt	39.20
23	1 pc	Spare Tyre Wheel Jack Sponge			cut	162.50

5,740.50

Less 20% 1,148.10

4,592.40

3899.80

3119.84

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle Number : SMS 6689U

B/F

4,592.40

Special Nett

1	1 set	Body Panel Joint Sealer		40	120.00
2	1 set	Reverse Sensor		200nw ✓	250.00
3	1 pc	Rear Exhaust Chrome Pipe		nt ✓	140.00
4	1 pc	Rear Number Plate With Holder		x n-	50.00

280

Labour charge

Panel Beating		1200	1,600.00
Spray painting (Pearl)		1000	1,200.00
Check Wiring		30	40.00
Anti rust		30	90.00
Remove and install reverse sensor		30	90.00
Remove and install carpet and seat		60	120.00

8,292.40

2350

Less 20% 1,658.48

Lump sum 6,633.92

Taufik 97495749
 'wp' 24/11/20 a 11am
 Comp on, Resurvey after repair
 7 days + 8 days
 Taufik C Lkk auto.wn

5849.84
 45\$ 4700
 Seley.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: