

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC6/AIG20012896/UGA3Q2

**Date:** 19/04/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070104654

**Claimant**  
**Vehicle No :** SJR732H **Insured Vehicle No :** SMT6678X

Date of Loss: 22/11/2020 Nature of Claim: TP Claim No: 6574125726SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJR732H	Engine No:	A2190073N20B20A
Make & Model:	BMW Z4, 2.0 (A)	Chassis No:	WBALL32030E750091
Reg. Date:	20/01/2012 (Man. Year: 2011)	Odometer:	51737 km
Colour:	White		
Engine Capacity:	1997 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

### CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,798.20	5,981.25	2,816.95	32.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,120.00	1,070.00	2,050.00	65.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>11,918.20</b>	<b>7,051.25</b>	<b>4,866.95</b>	<b>40.84</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>6,300.00</b>		
<b>(\$\$)</b>	11,918.20	6,300.00	5,618.20	47.14
<b>+ GST 7.00/7.00% (\$\$)</b>	834.27	441.00	393.27	47.14
<b>Nett Amount (\$\$)</b>	<b>12,752.47</b>	<b>6,741.00</b>	<b>6,011.47</b>	<b>47.14</b>
<b>+ Loss of Use (5.0 x S\$100.00/day) (\$\$)</b>		500.00		
<b>+ Doc/Search Fee (\$\$)</b>		2.00		
<b>Nett Liability (\$\$)</b>		<b>7,243.00</b>		

### INSPECTION

Date of Assignment: 24/11/2020

Date Inspected: 24/11/2020 Inspected At:

Specialists Motor Pte Ltd (HQ)  
Blk 3018A Ubi Road 1, #01-24/25/26  
Singapore 408711

Estimated Period of Repair: 3.0 days

---

**Adjuster:** MARCUS CHUA**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Dented / Bent	2,650.05 F	*2,650.05 FL
2	1		*SET BONNET INSULATOR CLIPS	Not Necessary	105.00 F	*- FL
3	1		*HEADLAMP ASSY RH	Cracked	2,449.90 F	*2,449.90 FL
4	1		*FRONT BUMPER FASCIA	Torn	1,109.65 F	*1,109.65 FL
5	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
6	1		*FRONT BUMPER BRACKET RH	Cracked	36.45 F	*36.45 FL
7	1		*FRONT WHEEL RIM RH (CUT)	Not Consistent With The Impact	1,912.15 FS	*- FS
8	1		*FRONT WHEEL TYRE RH (CUT)	Not Consistent With The Impact	485.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>8,798.20</b>	<b>6,296.05</b>
<b>- List Item Discount on L Items 0.00/5.00% (\$)</b>	<b>0.00</b>	<b>314.80</b>
<b>Total Parts (\$)</b>	<b>8,798.20</b>	<b>5,981.25</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	CUT OUT ,RENEW KNOCKING & WELDING FRONT BODY INNER PANEL ,REMOVE & INSTALL ALL DAMAGE PATS ,STRAIGHTEN & RE-ALIGN BODY }	New	600.00	400.00
2	REMOVE & REFIX HEADLAMP RH ,FRONT BUMPER FASCIA ,HEADLAMP WASHER JET RH & ETC }	New	520.00	0.00
3	REMOVE & REFIX FRONT BUMPER SENSOR	New	100.00	40.00
4	SPRAY PAINTING ON DAMAGE PARTS	New	1,200.00	500.00
5	CHECK ALL LIGHTING AFTER REPAIRS	New	80.00	20.00
6	TUFF-KOTE ON DAMAGE PARTS	New	40.00	30.00
7	DIAGNOSTIC CHECK & RESET	New	400.00	80.00
8	COMPUTERIZE WHEEL ALIGNMENT	New	180.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,120.00</b>	<b>1,070.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >