

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SJR732H/2011110

23th November 2020

The Manager
Motor Claim Department
AIG Asia Pacific Insurance Pte Ltd
CHARTIS Building
78 Shenton Way #07-16
Singapore 079120

Date of Accident : 22th November 2020
Location : 3 Tanjong Rhu Road Basement Carpark
Third Party Claim Vehicle No : SMT 6678 X (Your Insured)
Repair Cost For Vehicle No : SJR 732 H BMW Z4

NOT Acknowled
LH
24/11/20
2/5
3 days.
Whistle Blowing

Repair Sum \$ 6300

Estimate Supply of Parts & Labours:-

No.	Particulars	Qty	Price	Amounts
1	Bonnet <i>sent</i>	1	2,650.05	\$ 2,650.05
2	Bonnet insulator clips <i>11</i>	1set	105.00	\$ 105.00 X
3	Headlamp assy RH <i>one</i>	1	2,449.90	\$ 2,449.90
4	Front bumper fascia <i>to in</i>	1	1,109.65	\$ 1,109.65
5	Front bumper clips <i>nu</i>	1set	50.00	\$ 50.00
6	Front bumper bracket RH <i>one</i>	1	36.45	\$ 36.45
7	Front wheel Rim RH (s/nett) <i>cut/n/c</i>	1	1,912.15	\$ 1,912.15 X
8	Front wheel tyre RH (s/nett) <i>cut/n/c</i>	1	485.00	\$ 485.00 X
				\$ 8,798.20

(52)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

9-6286.05
57
9-5981.24
2-1070.20
7051.24
102
6346

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SJR732H/2011110

23th November 2020

Balance b/f	\$ 8,798.20
<u>Labour Charges :-</u>	<u>Amounts</u>
Cut out, renew, knocking & welding front body inner panel, remove & install all damage parts, straighten & re-align body	\$ 600.00 400
Remove & refix headlamp RH, front bumper fascia, headlamp washer jet RH & etc	\$ 520.00
Remove & refix front bumper sensor	\$ 100.00 40
Spray painting on damage parts	\$ 1,200.00 500
Check all lighting after repairs	\$ 80.00 20
Tuff-kote on damage parts	\$ 40.00 30
Diagnostic check & reset	\$ 400.00 80
Computerize wheel alignment	17 \$ 180.00 X
Labour Charge	\$ 3,120.00 1070
Total Amount	\$11,918.20

GST will be reflected in the final bills.

Notes : -Please inform us within 14 days, from the date of this letter, in the event that the owner/driver is in breach of its policy with your company, failing which we shall hold your company liable for all costs of repairs, loss of use and storage.