

NOT Authorized
 612sq & 3750k
 Presuming After Paint

Kp



5 days

ESTIMATE TO REPAIR

VEHICLE NO. : SKX 9960 M
 MAKE : HONDA
 MODEL : VEZEL 1.5X A
 YEAR : 2015
 CHASSIS NO : RU11105086

SURVEYOR NAME	Eric Kenneth
DATE OF SURVEY	24/11/20
TIME OF SURVEY	

DATE : 23-Nov-20
 DATE OF ACCIDENT : 21-Nov-20
 THIRD PARTY REF : SMG 6952 Y
 THIRD PARTY REF : AIG ASIA PACIFIC INSURANCE PTE LTD

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	rear bumper				\$ 508.50
10 pcs	rear bumper clips				\$ 35.00
2 pcs	rear bumper side cover		\$ 3.50		\$ 7.00
2 pcs	rear bumper retainer		\$ 195.00		\$ 390.00
1 pc	rear end panel		\$ 27.50		\$ 27.50
1 pc	rear end panel garnish				\$ 411.90
1 pc	rear end panel lower cover				\$ 152.30
1 pc	rear spare tyre top cover				\$ 260.00
1 pc	rear spare tyre tray				\$ 206.20
1 pc	tail gate				\$ 156.00
1 pc	tail gate VEZEL emblem				\$ 1,050.00
1 pc	tail gate lock				\$ 48.00
1 pc	tail gate rubber				\$ 200.10
1 pc	tail gate inner trim				\$ 142.30
1 pc	tail gate inner handle cover				\$ 159.40
1 pc	tail gate lamp				\$ 25.00
1 set	o/s tail lamp				\$ 296.60
	rear windscreen moulding				\$ 482.40
	Less 20%				\$ 140.00
					\$ 4,712.70
					\$ 942.54
					\$ 3,770.16
1 set	rear bumper sensor	S.NETT		3897.90	\$ 200.00
1 tube	rear windscreen sealant	S.NETT			\$ 40.00
	Towing fee		less 20%	3118.32	\$ 71.15
	To putty & spray paint		SN	311.15	\$ 60.00
	To transfer tail gate fitting		Lab	1320	\$ 80.00
	To remove and refix rear windscreen glass				\$ 100.00
	To anti-rust				\$ 80.00
	Labour charges.			4749.47	\$ 80.00
			less 20%	949.90	\$ 650.00
TG/VL	TOTAL				\$ 5,580.16
			LS	3799.57	
				3750.00	

Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721
 Tel: 65-64520893 Fax: 65-64589127 Email: edmund@lrm.sg
 Co. Reg No. 199307277D GST Reg No. M2-0019086-0

This document must not be reproduced, in whole or in part, or disclosed to third party or parties without prior written consent of Lim Tan Motor Pte Ltd

APPROVED

3/12/20