



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
UNITED OVERSEAS INSURANCE LTD 3 ANSON ROAD #28-01 SPRINGLEAF TOWER SINGAPORE 079909			Ref: CS/UOI20012899/Usd3e2	
			Date: 22/12/2020	
			Code: UOI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SJM 6778M	Veh. Inspected	SKS 9885Z
	Policy No.		Coverage (\$)	0.00
	Claim No.	M11D11342012	Excess (\$)	0.00
	Assign From	JOSEPHINE WONG	Assign Date	23/11/2020
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	MAZDA CX-5 (A)	c.c	1998
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	JM6KF2W7AK0241922	Colour	BLUE
	Odometer	34581 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	225/65 R17	YOKOHAMA	7 mm
	L/H Front Tyre	225/65 R17	YOKOHAMA	7 mm
	R/H Rear Tyre	225/65 R17	YOKOHAMA	7 mm
	L/H Rear Tyre	225/65 R17	YOKOHAMA	7 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	21/11/2020	Inspection Date	23/11/2020
	Survey held at	15 KAKI BUKIT ROAD 4# 01-53		
	Repairer	ZOOM AUTOWERKS PTE LTD		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	