

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No: 199607198R GST Reg. No. 19-9607198-R				
Affiliated to Federation Internationale Des Experts En Automobile					
AUTO) & GENERAL IN	SURANCE (S) PL	Ref : CS/AGI20012906/	Etf3e2	
(BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Date: 11-12-2020		
			Code: AGI		
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SJT 5387C	Veh. Inspected	SGK 4500G	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	C10008044/ST	Excess (\$)	0.00	
	Assign From	IVY RATILLA	Assign Date	23/11/2020	
2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA BELTA	c.c	996	
	Engine No.	HIDDEN	Year of Reg.	2006	
	Chassis No.	KSP921003406	Colour	BEIGE	
	Odometer	128466	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	FAIR			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	185/55 R15	BRIDGESTONE	5 mm	
	L/H Front Tyre	185/55 R15	BRIDGESTONE	5 mm	
	R/H Rear Tyre	185/55 R15	BRIDGESTONE	5 mm	
	L/H Rear Tyre	185/55 R15	BRIDGESTONE	5 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	5. General Information				
	Accident Date	19/11/2020	Inspection Date	24/11/2020	
	Survey held at	8 KAKI BUKIT AVENUE 4 PREMIER			
	Repairer	1ST AUTO PRO PTE LTD			
5a.	n. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	. Estimate Days of Repair				

8 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: