

ASS. REC. BY:

Steve

REF:

CS/AG/20012906/Etf3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Rat. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Sum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No

SGK 4500G

Yr Regn:

14/8/06

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Belta

c.c 996

Colour:

Beige

A/C: Insured / Std / NI / N

Sp Reading

128466

T/Radio: Insured / Std / NI / N

Eng/No:

C/No:

KSP 921903426

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/55R15

R:

BS DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

19/11/20

D.O.A.

24/11/20

Survey held at

1st Auto

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

MV-31K

PV-26,065

NV-4935

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp

(\$

☐

: Interview

(\$

☐

: Tech. Invs

(\$

☐

: Weekend

(\$

\$ + RS. \$

Photos

Others

Pop. Form:

Form 11/1/11



1st Auto Pro Pte Ltd

We Believe In Service

8 KAKI BUKIT AVENUE 4 PREMIER @ KAKI BUKIT #01-49 & #01-51/52 SINGAPORE 415875
Tel : 9188 3197 / 8614 6767 | Email: christina@1ap.com.sg

ESTIMATION QUOTE

BUDGET DIRECT INSURANCE
190 CLEMENCEAU AVENUE
#03-01 SINGAPORE SHOPPING CENTRE
SINGAPORE 239924
ATTN: MOTOR CLAIMS DEPARTMENT

Store (LKK) wil PL
24/11/20, 2.4pm
L/S
Ry AL 17.8 d/s

VEHICLE NO : SGK4500G
MAKE MODEL : TOYOTA BELTA
REFERENCE : 1AP-202011-25
DOA : 19-Nov-20
CLAIM TYPE : TP CLAIM

PAGE 1 OF 2

LIST ITEMS	QTY	LIST PRICE (\$)	REMARKS
BOOTLID / <i>DT</i>	1	\$ 1,493.00	
BOOTLID EMBLEM - LOGO / <i>APC</i>	1	\$ 159.90	
BOOTLID EMBLEM - BELTA / <i>APC</i>	1	\$ 168.50	
BOOTLID OUTER CHROME MOULDING <i>?</i>	1	\$ 314.50	
BOOTLID LOCK SWITCH <i>X</i>	1	\$ 298.00	
BOOTLID INNER LOCK / <i>DT</i>	1	\$ 385.20	
BOOTLID LOCK STRICKER <i>X</i>	1	\$ 132.00	
BOOTLID LOCK SENSOR <i>X</i>	1	\$ 212.00	
BOOTLID WEATHERSTRIP / <i>TAI</i>	1	\$ 311.60	
BOOTLID INNER TRIM <i>X</i>	1	\$ 398.60	
BOOTLID HINGES LH / RH / <i>BT</i>	2	\$ 474.00	
BOOTLID STOPPER RUBBER <i>X</i>	1 SET	\$ 160.00	
REAR NUMBER PLATE LAMP <i>X</i>	1 SET	\$ 191.00	
REAR BUMPER / <i>DD</i>	1 SET	\$ 1,085.90	
REAR BUMPER SIDE RETAINER LH / RH / <i>BR</i>	2	\$ 316.40	
REAR BUMPER SIDE BRACKET LH / RH / <i>BR</i>	2	\$ 237.00	
REAR BUMPER REINFORCEMENT <i>?</i>	1	\$ 479.00	
REAR END PANEL / <i>DD</i>	1	\$ 761.10	
REAR END PANEL TOP GARNISH / <i>CR4</i>	1	\$ 340.90	
SPARE TYRE PANEL <i>?</i>	1	\$ 837.70	
SPARE TYRE PANEL TOP BOARD <i>?</i>	1	\$ 541.30	
EXHAUST MUFFLER <i>X</i>	1	\$ 793.10	
EXHAUST MOUNTING <i>X</i>	1	\$ 176.20	
TAILLAMP LH / RH / <i>BR</i>	2	\$ 1,389.20	
REAR FENDER INNER TRIM LH / RH <i>X</i>	2	\$ 978.00	

\$ 12,634.10

LESS 25% \$ 3,158.53

SUBTOTAL \$ 9,475.58

BALANCE C/F \$ 9,475.58

SPECIAL NETT ITEMS	QTY	LIST PRICE (\$)	REMARKS
BALANCE B/F	\$	9,475.58	
BOOTLID OUTER CHROME MOULDING CLIPS <i>?</i>	1 SET	\$ 50.00	
BOOTLID INNER TRIM CLIPS <i>X</i>	1 SET	\$ 50.00	

ESTIMATION QUOTE

BUDGET DIRECT INSURANCE
190 CLEMENCEAU AVENUE
#03-01 SINGAPORE SHOPPING CENTRE
SINGAPORE 239924
ATTN: MOTOR CLAIMS DEPARTMENT

VEHICLE NO : SGK4500G
MAKE MODEL : TOYOTA BELTA
REFERENCE : 1AP-202011-25
DOA : 19-Nov-20
CLAIM TYPE : TP CLAIM

PAGE 2 OF 2

SPECIAL NETT ITEMS	QTY	LIST PRICE (\$)	REMARKS
REAR BUMPER CLIPS <i>MC</i>	1 SET	\$ 50.00	30
REAR BUMPER SIDE CLIPS <i>X</i>	1 SET	\$ 50.00	
REAR END PANEL TOP GARNISH CLIPS <i>MC</i>	1 SET	\$ 50.00	10
TAILLAMP CLIPS <i>X</i>	1 SET	\$ 50.00	
REAR FENDER INNER TRIM CLIPS <i>X</i>	1 SET	\$ 50.00	
REAR NUMBER PLATE WITH HOLDER <i>X</i>	1	\$ 100.00	
REVERSE SENSOR <i>X</i> <i>MC</i>	1 SET	\$ 200.00	

SUBTOTAL \$ 650.00

BALANCE C/F \$ 10,125.58

LABOUR	S/NO	LIST PRICE (\$)	REMARKS
--------	------	-----------------	---------

BALANCE B/F \$ 10,125.58

TO REMOVE, REFIT AND TRANSFER REAR BOOT COMPONENT	1	\$ 250.00	50
TO REMOVE AND REFIT ELECTRICAL WIRING, REPLACE DAMAGED LAMPS AND TEST FOR PROPER FUNCTIONING	2	\$ 250.00	30
TO REMOVE AND REFIT INNER TRIMS AND GARNISHES TO FACILITATE THE REPAIR	3	\$ 250.00	50
TO REMOVE AND REFIT REAR BUMPER SENSOR	4	\$ 100.00	30
TO REMOVE AND REFIT, STRAIGHTEN AND RE-ADJUST EXHAUST PIPE AND REPLACE REAR EXHAUST SILENCER AND MOUNTING	5	\$ 350.00	X
TO APPLY UNDERCOATING ON REPLACED AND REPAIRED PANELS FOR RUST PROTECTION	6	\$ 100.00	30
TO PROVIDE SPRAY PAINTING ON THE REPLACED AND REPAIRED PARTS	7	\$ 2,000.00	1000
TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS. TO RE-ADJUST TO ORIGINAL POSITION USING POWER TOOLS	8	\$ 2,000.00	1000

SUBTOTAL \$ 5,300.00

GRAND TOTAL \$ 15,425.58

- ACKNOWLEDGEMENT BY REPAIRER**
- I, the undersigned, hereby acknowledge that I have received the above estimate and I agree to the terms and conditions of the estimate.
- To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer