



1st Auto Pro Pte Ltd

We Believe In Service

8 KAKI BUKIT AVENUE 4 PREMIER @ KAKI BUKIT #01-49 & #01-51/52 SINGAPORE 415875

Tel : 9188 3197 / 8614 6767 | Email: christina@1ap.com.sg

ESTIMATION QUOTE

BUDGET DIRECT INSURANCE
190 CLEMENCEAU AVENUE
#03-01 SINGAPORE SHOPPING CENTRE
SINGAPORE 239924
ATTN: MOTOR CLAIMS DEPARTMENT

Steve (LKK) wtl ml
24/11/20, 2.10pm
L/S
By AL 27.8 d/s

VEHICLE NO : SGK4500G
MAKE MODEL : TOYOTA BELTA
REFERENCE : 1AP-202011-25
DOA : 19-Nov-20
CLAIM TYPE : TP CLAIM

PAGE 1 OF 2

LIST ITEMS	QTY	LIST PRICE (\$)	REMARKS
BOOTLID / DP	1	\$ 1,493.00	528 ✓
BOOTLID EMBLEM - LOGO / RL	1	\$ 159.90	58 ✓
BOOTLID EMBLEM - BELTA / RL	1	\$ 168.50	55 ✓
BOOTLID OUTER CHROME MOULDING / X NM	1	\$ 314.50	
BOOTLID LOCK SWITCH X NM	1	\$ 298.00	
BOOTLID INNER LOCK / BT	1	\$ 385.20	109 ✓
BOOTLID LOCK STRICKER X NM	1	\$ 132.00	
BOOTLID LOCK SENSOR X NM	1	\$ 212.00	
BOOTLID WEATHERSTRIP / TM	1	\$ 311.60	180 ✓
BOOTLID INNER TRIM X NM	1	\$ 398.60	
BOOTLID HINGES LH / RH / BT	2	\$ 474.00	300 ✓
BOOTLID STOPPER RUBBER X NM	1 SET	\$ 160.00	
REAR NUMBER PLATE LAMP X NM	1 SET	\$ 191.00	
REAR BUMPER / DP	1 SET	\$ 1,085.90	491 ✓
REAR BUMPER SIDE RETAINER LH / RH / BR	2	\$ 316.40	130 ✓
REAR BUMPER SIDE BRACKET LH / RH / BR	2	\$ 237.00	110 ✓
REAR BUMPER REINFORCEMENT / X NM	1	\$ 479.00	
REAR END PANEL / DP	1	\$ 761.10	552 ✓
REAR END PANEL TOP GARNISH / CR4	1	\$ 340.90	185 ✓
SPARE TYRE PANEL / X R	1	\$ 837.70	
SPARE TYRE PANEL TOP BOARD / X NM	1	\$ 541.30	
EXHAUST MUFFLER X NM	1	\$ 793.10	
EXHAUST MOUNTING X NM	1	\$ 176.20	
TAILLAMP LH / RH / BR	2	\$ 1,389.20	794
REAR FENDER INNER TRIM LH / RH X NM	2	\$ 978.00	794 ✓

\$ 12,634.10

LESS 25% \$ 3,158.53

SUBTOTAL \$ 9,475.58

BALANCE C/F \$ 9,475.58

SPECIAL NETT ITEMS	QTY	LIST PRICE (\$)	REMARKS
BALANCE B/F		\$ 9,475.58	
BOOTLID OUTER CHROME MOULDING CLIPS / X NM	1 SET	\$ 50.00	
BOOTLID INNER TRIM CLIPS X NM	1 SET	\$ 50.00	

3492
-25%
2619

ESTIMATION QUOTE

BUDGET DIRECT INSURANCE
190 CLEMENCEAU AVENUE
#03-01 SINGAPORE SHOPPING CENTRE
SINGAPORE 239924
ATTN: MOTOR CLAIMS DEPARTMENT

VEHICLE NO : SGK4500G
MAKE MODEL : TOYOTA BELTA
REFERENCE : 1AP-202011-25
DOA : 19-Nov-20
CLAIM TYPE : TP CLAIM

PAGE 2 OF 2

SPECIAL NETT ITEMS	QTY	LIST PRICE (\$)	REMARKS
REAR BUMPER CLIPS <i>NR</i>	1 SET	\$ 50.00	<i>30</i>
REAR BUMPER SIDE CLIPS <i>NR</i>	1 SET	\$ 50.00	
REAR END PANEL TOP GARNISH CLIPS <i>NR</i>	1 SET	\$ 50.00	<i>10</i>
TAILLAMP CLIPS <i>NR</i>	1 SET	\$ 50.00	
REAR FENDER INNER TRIM CLIPS <i>NR</i>	1 SET	\$ 50.00	
REAR NUMBER PLATE WITH HOLDER <i>NR</i>	1	\$ 100.00	
REVERSE SENSOR <i>NR</i>	1 SET	\$ 200.00	
SUBTOTAL		\$ 650.00	<i>240</i>
BALANCE C/F		\$ 10,125.58	

LABOUR	S/NO	LIST PRICE (\$)	REMARKS
BALANCE B/F		\$ 10,125.58	

TO REMOVE, REFIT AND TRANSFER REAR BOOT COMPONENT	1	\$ 250.00	<i>50</i>
TO REMOVE AND REFIT ELECTRICAL WIRING, REPLACE DAMAGED LAMPS AND TEST FOR PROPER FUNCTIONING	2	\$ 250.00	<i>30</i>
TO REMOVE AND REFIT INNER TRIMS AND GARNISHES TO FACILITATE THE REPAIR	3	\$ 250.00	<i>50</i>
TO REMOVE AND REFIT REAR BUMPER SENSOR	4	\$ 100.00	<i>30</i>
TO REMOVE AND REFIT, STRAIGHTEN AND RE-ADJUST EXHAUST PIPE AND REPLACE REAR EXHAUST SILENCER AND MOUNTING	5	\$ 350.00	<i>X</i>
TO APPLY UNDERCOATING ON REPLACED AND REPAIRED PANELS FOR RUST PROTECTION	6	\$ 100.00	<i>30</i>
TO PROVIDE SPRAY PAINTING ON THE REPLACED AND REPAIRED PARTS	7	\$ 2,000.00	<i>1000</i>
TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS. TO RE-ADJUST TO ORIGINAL POSITION USING POWER TOOLS	8	\$ 2,000.00	<i>1000</i>

SUBTOTAL \$ 5,300.00

GRAND TOTAL \$ 15,425.58

- LK Auto Consultants hence notify the Repairer of the following:*
- To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: