

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

23 NOV 2020

Estimate No. : b1 56643
Date Estimated : 23/11/2020
Prepared By : Foong Shiuh Jye

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

April Zeng Xiuling Mrs April Hong Xiuling
1005 Lower Delta Road
#15-02

Singapore 099309

- ACCOUNT - 219

India Int'L Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLU207T	WBA2D920305E91648	21/11/2017	216i G TOURER	0

DESCRIPTION	VALUE
To replace both right doors, right side rear panel. 1 1/2 5-5 65 * Rear Bumper 1 day 1850	6375 8,075.00
To remove and install side sill cover 1/2	
To spray paint both right doors, rear right side panel, right side sill cover, both door handles. 2 - 885 x 7 1 - 885 * Rear Bumper 1 panel 974 3430	3,812.00
Roof frame right, running board right panel, tail panel - 10% 1008	
To transfer lock mechanism from old to new door including conduct check on new door power window system for proper function. (2 door).	955 1,062.00
To replace rear door fixed side window glass. *rear right door	398.00
To replace rear side window glass. *rear right side panel	398.00
To supply and install rear right window glass solar film. *rear right side panel	500.00
To supply and install rear right window glass solar film. *rear door fixed glass	500.00
To conduct water leak tests.	75.00
To replace wheelrim rear right including balancing. (1x).	94.00
To check steering geometry and conduct wheel alignment in accordance with BMW specifications. (1x).	478 531.00
To remove and install rear seats and carpet to facilitate repair. (photo)	783 870.00
Sundries + To remove and install fuel tank \$531.00 / 478 (photo) ?	150.00

Spray paint wheel rim rear right \$250.00

(NT Repair)

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : **b1 56643**
Date Estimated : **23/11/2020**
Prepared By : **Foong Shiuh Jye**

Page No. : **2 of 5**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLU207T	WBA2D920305E91648	21/11/2017	216i G TOURER	0

Total Labour 1: **16,465.00**

DESCRIPTION	QTY	PRIC	VALUE
PLASTIC NUT FOR COARSE THREADED PIN / <i>nk</i>	6	0.85	5.10
BLIND RIVET NUT WITH COLLAR M5 / <i>nk</i>	1	5.55	5.55
COLLAR SCREW / <i>nk</i>	1	3.65	3.65
ALLOY RIM 7JX16 DOUBLE SPK 473 X	1	764.50	764.50
REAR RH SIDE PANEL / <i>nk</i>	1	1,466.65	1,466.65
POTSDITIONING AID T-AID / <i>nk</i>	1	5.80	5.80
REINFORCEMENT PLATE UNIVERSAL / <i>nk</i>	1	52.50	52.50
RH REINFORCEMENT PLATE SILL / <i>nk</i>	1	53.75	53.75
RH REINFORCEMENT PLATE C PILLAR / <i>nk</i>	1	53.75	53.75
RH REINFORCEMENT PLATE D PILLAR / <i>nk</i>	1	53.75	53.75
T WELD BOLT L=5.4MM / <i>nk</i>	10	0.90	9.00
FRT RH DOOR X <i>nk</i>	1	1,136.90	1,136.90
RR RH DOOR / <i>nk</i>	1	1,136.90	1,136.90
PLASTIC NUT / <i>nk</i>	4	0.85	3.40
DOOR HANDLE PAINTED OUTER RH (A96 M X	1	533.55	533.55
RH DOOR OUTER HANDLE PRIMED X	1	95.55	95.55
RH SEALING COLUMN B BOTTOM / <i>nk</i>	1	54.60	54.60
REAR RH SIDE WINDOW FIXED (ALU HOCH / <i>nk</i>	1	278.45	278.45
RH FIXED DOOR WINDOW / <i>nk</i>	1	131.15	131.15
CAVITY PROTECTION WAX REMOVER 500ML / <i>nk</i>	1	18.45	18.45
BLIND RIVET AVIBVLB / <i>nk</i>	8	0.55	4.40
SCREW (SF PLUS M5X15) / <i>nk</i>	3	0.55	1.65
(DG/SL) BODY ADHESIVE K5B (195ML) / <i>nk</i>	1	331.80	331.80
(DG) BODYWORK ADHESIVE K5A (50ML) / <i>nk</i>	1	114.45	114.45
(DG) CLEANER R1 (100ML) / <i>nk</i>	1	26.15	26.15
PUNCH RIVET N4 / <i>nk</i>	36	0.55	19.80

Total Parts : **6,361.20**

ster (LKK)

*WHL P/L
4/12/20, 10-11am*

P/P

By BeL spj

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- is subject to confirmation
- is on a "Without Prejudice" basis
- ification(s) is allowed
- item(s) must be resurveyed and
- ial approval from insurance Company



Acknowledged by Repairer

Signature:

10 days

Labour 1	:	16,465.00
Parts	:	6,361.20
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,597.83
Grand Total	:	24,424.03

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **