

RICO60

AUTO SERVICES

Rico 60 Auto Services Pte Ltd
Blk 8 , Kaki Bukit Avenue 4 , #02-24
Premier @ Kaki Bukit Singapore 415875
Email: claims@rico60.com
Tel: 6286 6060 Fax : 6286 7060

RICO Office Use Only

Parts -%	
SN	
Labour	
Lump Sum	
ERV	\$ 15,700.00

TO: AIG

Vehicle No : SLA 3220 P

Make & Model : HONDA VEZEL

DATE:19/11/2020

No.	DESCRIPTION - PARTS	QTY	UNIT PRICE	PRICE
1	BONNET <i>Painted</i>	1	\$ 976.50	\$ 976.50
2	BONNET CENTER RUBBER <i>New</i>	2	\$ 44.00	\$ 88.00
3	BONNET SIDE RUBBER <i>New</i>	2	\$ 56.00	\$ 112.00
4	BONNET INNER LOCK <i>New</i>	1	\$ 281.00	\$ 281.00
5	BONNET HINGE <i>New</i>	2	\$ 132.70	\$ 265.40
6	HEAD LAMP <i>Cracked</i>	2	\$ 1,890.00	\$ 3,780.00
7	HEAD LAMP SIDE BRACKET <i>New</i>	2	\$ 75.40	\$ 150.80
8	HEAD LAMP LOWER HOLDER <i>Cracked</i>	2	\$ 141.50	\$ 283.00
9	FRONT GRILLE <i>Cracked</i>	1	\$ 375.40	\$ 375.40
10	FRONT GRILLE BADGE <i>New</i>	1	\$ 67.30	\$ 67.30
11	FRONT GRILLE OUTER PAD <i>lit</i>	1	\$ 276.40	\$ 276.40
12	FRONT GRILLE CHROME MOULDING <i>lit</i>	2	\$ 76.90	\$ 153.80
13	FRONT GRILLE TOP SUPPORTOR <i>Cracked</i>	1	\$ 166.80	\$ 166.80
14	FRONT BUMPER <i>Painted</i>	1	\$ 489.80	\$ 489.80
15	FRONT BUMPER SIDE RETAINER <i>New</i>	2	\$ 85.00	\$ 170.00
16	FRONT BUMPER LOWER SIDE BRACKET <i>New</i>	2	\$ 75.00	\$ 150.00
17	FRONT BUMPER TOWING COVER <i>New</i>	1	\$ 57.30	\$ 57.30
18	FRONT BUMPER REINFORCEMENT <i>Best</i>	1	\$ 625.40	\$ 625.40
19	FRONT BUMPER REINFORCEMENT RUBBER <i>New</i>	2	\$ 72.00	\$ 144.00
20	FRONT BUMPER LOWER GRILLE <i>Painted</i>	1	\$ 321.00	\$ 321.00
21	FRONT BUMPER FOG LAMP <i>New</i>	2	\$ 398.00	\$ 796.00
22	FRONT BUMPER FOG LAMP COVER <i>New</i>	2	\$ 161.00	\$ 322.00
23	FRONT BUMPER LOWER DIFFUSER <i>New</i>	1	\$ 279.60	\$ 279.60
24	FRONT BUMPER UNDER COVER <i>New</i>	1	\$ 317.00	\$ 317.00
25	FRONT WHEEL ARCH GARNISH <i>New</i>	2	\$ 389.70	\$ 779.40
26	SUPPORT PANEL <i>Best</i>	1	\$ 689.00	\$ 689.00
27	SUPPORT TOP GARNISH <i>Painted</i>	1	\$ 244.30	\$ 244.30

95

28	OUTER TEMPERATURE SENSOR <i>New</i>	1	\$	398.00	\$	398.00	+
29	RADIATOR CAP HEAD <i>New</i>	1	\$	165.00	\$	165.00	+
30	FRONT AIR DUCT <i>could</i>	1	\$	172.10	\$	172.10	77.50
31	AIR CON CONDENSER <i>Best</i>	1	\$	658.10	\$	658.10	✓
32	AIR CON CONDENSER SIDE GUIDE <i>New</i>	2	\$	62.50	\$	125.00	+
33	AIR CON CONDENSER SIDE MOUNTING <i>New</i>	2	\$	63.20	\$	126.40	+
34	RADIATOR <i>New</i>	1	\$	1,250.60	\$	1,250.60	+

				8178.60		
				6542.88		
				Subtotal :	\$	15,256.40
				Less 20%	\$	3,051.28
				Parts Total :	\$	12,205.12

NO.	SPECIAL NETT	QTY	UNIT PRICE	PRICE
1	BONNET CENTER RUBBER CLIP SET <i>New</i>	1	\$ 30.00	\$ 30.00 <i>+</i>
2	BONNET SIDE RUBBER CLIP SET <i>New</i>	1	\$ 30.00	\$ 30.00 <i>+</i>
3	HEAD LAMP BULK SET <i>New</i>	1	\$ 80.00	\$ 80.00 <i>+</i>
4	FRONT GRILLE CLIP SET <i>New</i>	1	\$ 40.00	\$ 40.00 <i>20</i>
5	FRONT BUMPER CLIP SET <i>New</i>	1	\$ 50.00	\$ 50.00 <i>30</i>
6	FRONT BUMPER FOG LAMP BULK <i>New</i>	1	\$ 30.00	\$ 30.00 <i>+</i>
7	FRONT BUMPER UNDER COVER CLIP SET <i>New</i>	1	\$ 40.00	\$ 40.00 <i>+</i>
8	SUPPORT PANEL SEALANT <i>New</i>	1	\$ 80.00	\$ 80.00 <i>+</i>
9	SUPPORT TOP GARNISH CLIP SET <i>New</i>	1	\$ 40.00	\$ 40.00 <i>20</i>
10	RADIATOR COOLANT <i>New</i>	1	\$ 50.00	\$ 50.00 <i>40</i>
11	FRONT NUMBER PLATE WITH BASE <i>Cracked</i>	1	\$ 80.00	\$ 80.00 <i>60</i>
			<i>170</i>	
				\$ 550.00

LABOUR	PRICE
PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,400.00 600
TO SPRAY PAINT AFFECTED AREA	\$ 1,400.00 600
TO PERFORM LIGHTING & WIRING CHECK	\$ 100.00 30
TO APPLY ANTI-RUST & TUFF KOTE	\$ 200.00 40
REMOVE AND INSTALL RADIATOR AND REFILL COOLANT AND HIGH PRESSURE TEST	\$ 180.00 60
REMOVE AND INSTALL CONDENSER AND REFILL AIRCON GAS	\$ 180.00 60
1390	

LABOUR TOTAL		\$	3,460.00
--------------	--	----	----------

	Total Parts Cost	\$	12,755.12
	Total Labour Cost	\$	3,460.00
	Total Repair Cost	\$	16,215.12

APPROVED DETAILS

NO. OF WORKING DAYS

PART BY PART OR LUMP SUM

DATE & TIME OF SURVEY

SURVEYED BY

CONTACT NUMBER

FAX NUMBER

Adrian G
H/s 24/11/20
OSRys

Total: 8102.88.
H/s: 6.4K.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: