

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC3/TMI20012916/ESD3E2  
**Date:** 16/12/2020

### REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd	Policy No: MS010839
Claimant Vehicle No : SHC8905B	Insured Vehicle No : GBG6782B
Date of Loss: 21/11/2020	Nature of Claim: TP Claim No: M2005788

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: <b>SHC8905B</b>	Engine No: D4FDGU669076
Make & Model: HYUNDAI I40, 1.7 D (A)	Chassis No: KMHLB41UMGU087403
Reg. Date: 14/04/2016 (Man. Year: 2016)	Odometer: 689796 km
Colour: Blue	
Engine Capacity: 1685 cc	
Market Value/New Car Price: N/A	
Sum Insured (\$\$): <b>Market Value/New Car Price</b>	

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good	Steering (Serviceable): Yes	Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes	Engine Modification: No	Pre-accident Condition: Good

### CONDITION OF TYRES

Front Tyre Size: 205/60 R16	Rear Tyre Size: 205/60 R16
Front Left Side: Dunlop 5 mm	Rear Left Side: Dunlop 5 mm
Front Right Side: Dunlop 5 mm	Rear Right Side: Dunlop 5 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,533.76	1,740.80	1,792.96	50.74
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,340.00	510.00	830.00	61.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>4,884.76</b>	<b>2,261.80</b>	<b>2,622.96</b>	<b>53.70</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>1,800.00</b>		
<b>(\$\$)</b>	4,884.76	1,800.00	3,084.76	63.15
<b>+ GST 7.00/7.00% (\$\$)</b>	341.93	126.00	215.93	63.15
<b>Nett Amount (\$\$)</b>	<b>5,226.69</b>	<b>1,926.00</b>	<b>3,300.69</b>	<b>63.15</b>

### INSPECTION

Date of Assignment: 24/11/2020	Present Location: ComfortDelGro Engineering Pte Ltd (Loyang)	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected: 24/11/2020	Inspected At: 59 Loyang Drive	Singapore 508969
Estimated Period of Repair: 2.0 days		

**Adjuster:** CHEN TSUE YEE

**Manager:** Hiew May Fung

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but*

*any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 16 Dec 2020)
<b>Parts:</b>	143	HYUNDAI I40 1.7 D (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHC8905B)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*FRONT BUMPER	Not Necessary	1,052.20 FL	-	*- FL
2	1		*FRONT BUMPER BRACKET RH	Not Necessary	24.60 FL	-	*- FL
3	1		*FRONT FENDER RH	Dented	663.00 FL	-	*663.00 FL
4	1		*FRONT FENDER SHIELD RH	Not Necessary	174.90 FL	-	*- FL
5	1		*FRONT WHEEL COVER RH	Not Necessary	107.10 FL	-	*- FL
6	1		*HEAD SUPPORT PANEL	Not Necessary	907.40 FL	-	*- FL
7	1		*HEAD LAMP RH	Cut	1,388.00 FL	-	*1,388.00 FL
8	1		*FRT FENDER ADVERTISEMENT	Necessary	100.00 FL	-	*100.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>4,417.20</b>	<b>2,151.00</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	883.44	410.20
<b>Total Parts (\$\$)</b>	<b>3,533.76</b>	<b>1,740.80</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	600.00	280.00
2	SPRAY PAINTING	New	500.00	200.00
3	CHECK LIGHTING	New	60.00	30.00
4	REMOVE/REFIX AC CONDENSER & CHARGE GAS	New	120.00	0.00
5	REALIGN WHEEL ALIGNMENT	New	60.00	0.00
Gross Labour Cost (\$\$)			1,340.00	510.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >