



WAH HONG MOTORS & CREDIT PTE LTD

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Vehicle No. SJG6383A HONDA SHUTTLE 1.5G CVT

Page No. 1

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR'S ADJUSTMENT
<u>PARTS (LIST ITEMS)</u>				
1	Rear boot lid		1193.00	bt ✓
2	Rear boot lid hinge LH/RH @2*\$50		100.00	Ry ✓
2	Rear boot lid damper RH/LH @2*\$164		328.00	Ry ✓
1	Rear boot lid trim board		320.00	de ✓
1	Rear boot lid inner handler garnish		25.00	de ✓
1	Rear boot lid center outer chrome		384.00	? photo
1	Rear boot lid logo badge		38.00	de ✓
1	Rear boot lid lock		158.00	bt ✓
1	Rear windscreen moulding		120.00	rac ✓
2	Rear boot lid lamp RH/LH @2*\$395		790.00	? ✓
2	Rear tail lamp RH/LH @2*\$521		1042.00	int ✓
1	Rear bumper		1151.00	de ✓
2	Rear bumper side retainer RH/LH @2*\$27		54.00	de ✓
1	Rear bumper sponge		57.00	x
1	Rear end panel		561.00	bt ✓
1	Rear end panel TOP garnish		156.00	cuq ✓
1	Rear boot lid weather strip		169.00	hvi ✓
2	Rear fender inner trim garnish RH/LH @2*\$490		980.00	LH-de, RH x
1	Rear trunk storage compartment		245.00	ora ✓
1	Rear trunk top cover		350.00	x
1	Rear trunk floor panel		1980.00	Ry ✓
1	Rear bumper towing cover		17.00	de ✓
1	Rear bumper side reflector cover LH		45.00	ant ✓
			10263.00	
			-20%	-2052.60
			8210.40	
<u>SPECIAL NETT ITEMS</u>				
1	Rear bumper clips		35.00	30 ne ✓
1	Windscreen sealant		80.00	60 ne ✓
1	floor panel and end panel sealant		100.00	40 ne ✓
1	Car plate with holder		35.00	cuq ✓
1	Rear reverse sensor set		200.00	nuw ✓
Total Parts			8660.40	



WAH HONG MOTORS & CREDIT PTE LTD

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Vehicle No. SJG6383A HONDA SHUTTLE 1.5G CVT

Page No. 2

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$\$)	SURVEYOR'S ADJUSTMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	1600.00	1000
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	1200.00	900
3	To remove and re-fix rear windscreen	150.00	120
4	To remove and re-fix wiring system at accident damaged area and check all electrical & component for proper function	120.00	30
5	To perform anti-rust treatment on affected areas	120.00	40
6	To remove and refit/replace reverse sensor	120.00	30
7	To remove and refit/replace rear boot lid & rear trunk both side fitting, trimmings, garnish and etc	200.00	60
	Labour Total :	3510.00	
	TOTAL (PARTS & LABOUR):	12170.40	

Tanfah 97495749
 WP 24/11/2016/PM
 Lumpsum
 Resurvey after repair
 tanfah@lkkauto.com
 07days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: