

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5860R*Not Withheld**1/1/2020*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

18 NOV 2020**SHC5860R**

VF1ABL15AUC282338

RENAULT

LATITUDE

16/11/2020

CHINA

06/03/2015

	PART		LIST	
1	1 BUMPER COVER REAR	\$	<i>By</i> 561.70 ✓	
2	1 BUMPER LOWER REAR	\$	<i>nd/GM</i> 411.90 ✓	
3	1 BUMPER BRACKET CTR REAR	\$	<i>Sh</i> 98.10 X	
4	1 BUMPER BRACKET SIDE RH REAR	\$	<i>Sh</i> 82.10 X	
5	1 BUMPER RETAINER RH REAR	\$	<i>Sh</i> 59.80 X	
7	1 BUMPER BRACKET SIDE LH REAR	\$	<i>Sh</i> 80.80 X	
8	1 BUMPER RETAINER LH REAR	\$	<i>Sh</i> 54.20 X	
10	1 BUMPER BEAM REAR	\$	<i>By</i> 547.80 ✓	
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>R</i> 114.50 X	
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>R</i> 114.50 X	
13	1 OUTER PANEL REAR (End Panel)	\$	<i>By</i> 745.80 ✓	
14	1 OUTER PANEL REAR (End Panel)TRIM	\$	<i>Sh</i> 404.56 X	
15	1 BOOT REAR	\$	<i>By</i> 1,677.20 ✓	
16	1 BOOT REFLECTOR LAMP LH	\$	<i>CM</i> 277.70 ✓	
17	1 BOOT REFLECTOR LAMP RH	\$	<i>Sh</i> 277.70 X	
18	1 BOOT HINGE LH	\$	<i>R</i> 254.20 X	
19	1 BOOT HINGE RH	\$	<i>R</i> 254.20 X	
20	1 BOOT LOCK	\$	<i>R</i> 246.60 X	
21	1 BOOT LOCK CATCH	\$	<i>R</i> 41.70 X	
22	1 BOOT FINISHER	\$	<i>Sh</i> 344.70 X	
23	1 BOOT BADGE 'RENAULT'	\$	<i>Sh</i> 82.40 ✓	
24	1 BOOT BADGE	\$	<i>Sh</i> 95.80 ✓	
25	1 BOOT FINISHER	\$	<i>Sh</i> 344.70 X	
26	1 TAILLAMP RH	\$	<i>Sh</i> 401.40 X	
27	1 TAILLAMP LH	\$	<i>CM</i> 401.40 ✓	
		\$	7,975.46	
		10% \$	797.55	

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5860R

\$	7,177.91
----	-----------------

Special Nett

1 1SET PARKING AID	\$	Sm	700.00	X
2 1 BOOT FINISHER NUT L70Y	\$	Nn	60.00	X
3 1SET REAR BUMPER CLIP	\$	Nn	66.00	✓
4 1SET BUMPER BRACKET CTR CLIP	\$	Nn	33.00	X
5 1SET BUMPER BRACKET SIDE CLIP RH RR	\$	Nn	10.00	X
6 1SET BUMPER RETAINER RH CLIP RR	\$	Nn	20.00	X
7 1SET BUMPER BRACKET SIDE CLIP LH RR	\$	Nn	10.00	X
8 1SET BUMPER RETAINER CLIP LH RR	\$	Nn	20.00	X
9 1SET BUMPER LOWER REAR RIVET	\$	Nn	22.00	X
10 1SET BUMPER LOWER REAR CLIP	\$	Nn	66.00	✓
11 1 EXHAUST MOUNTING REAR	\$	Sh	17.82	X
12 1 REAR NUMBER PLATE WITH HOLDER	\$	Sh	120.00	X
13 1 REAR BOOT STICKER 'Trans-cab'	\$	Nn	80.00	30sm✓
14 1 REAR BOOT STICKER '6555-3333'	\$	Nn	80.00	30sm
TOTAL	\$		1,304.82	
TOTAL PARTS	\$		8,482.73	

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	660k
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00	600l
To Rust-Proofing Of The Affected Areas.	\$	170.00	60l
To reinstall rear bumper parking sensor.	\$	170.00	60l
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	60l
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	60l

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5860R

To check steering geometry and computer wheel alignment \$ *na* 220.00 *X*

To Check Electrical Lighting Concerned. \$ 170.00 *201*

TOTAL \$ 7,070.00

Over All Total \$ 22,730.65

(LUMP SUM)

Repair Days

20 DAYS

5 days

For Official Use

Prepared By : _____
(Accident Dept)

Verify By : _____
(Accident Workshop)

Checked By : _____
(Finance Dept)

LK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: