

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5860R*Not Authoised
1/1 Sep @ 4850/*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

10 NOV 2020

SHC5860R

VF1ABL15AUC282338

RENAULT

LATITUDE

16/11/2020

CHINA

06/03/2015

PART

- 1 1 BUMPER COVER REAR
- 2 1 BUMPER LOWER REAR
- 3 1 BUMPER BRACKET CTR REAR
- 4 1 BUMPER BRACKET SIDE RH REAR
- 5 1 BUMPER RETAINER RH REAR
- 7 1 BUMPER BRACKET SIDE LH REAR
- 8 1 BUMPER RETAINER LH REAR
- 10 1 BUMPER BEAM REAR
- 11 1 BUMPER BEAM BRACKET LH REAR
- 12 1 BUMPER BEAM BRACKET RH REAR
- 13 1 OUTER PANEL REAR (End Panel)
- 14 1 OUTER PANEL REAR (End Panel)TRIM
- 15 1 BOOT REAR
- 16 1 BOOT REFLECTOR LAMP LH
- 17 1 BOOT REFLECTOR LAMP RH
- 18 1 BOOT HINGE LH
- 19 1 BOOT HINGE RH
- 20 1 BOOT LOCK
- 21 1 BOOT LOCK CATCH
- 22 1 BOOT FINISHER
- 23 1 BOOT BADGE 'RENAULT'
- 24 1 BOOT BADGE
- 25 1 BOOT FINISHER
- 26 1 TAILLAMP RH
- 27 1 TAILLAMP LH

LIST

\$	<i>Bz</i>	561.70	✓
\$	<i>nd / Wt</i>	411.90	✓
\$	<i>Sn</i>	98.10	X
\$	<i>Sn</i>	82.10	X
\$	<i>Sn</i>	59.80	X
\$	<i>Sn</i>	80.80	X
\$	<i>Sn</i>	54.20	X
\$	<i>Bz</i>	547.80	✓
\$	<i>R</i>	114.50	X
\$	<i>R</i>	114.50	X
\$	<i>Bz</i>	745.80	✓
\$	<i>Sn</i>	404.56	X
\$	<i>Bz</i>	1,677.20	✓
\$	<i>CM</i>	277.70	✓
\$	<i>Sn</i>	277.70	X
\$	<i>R</i>	254.20	X
\$	<i>R</i>	254.20	X
\$	<i>R</i>	246.60	X
\$	<i>R</i>	41.70	X
\$	<i>Sn</i>	344.70	X
\$	<i>Sn</i>	82.40	✓
\$	<i>Sn</i>	95.80	✓
\$	<i>Sn</i>	344.70	X
\$	<i>Sn</i>	401.40	X
\$	<i>CM</i>	401.40	✓

\$ 7,975.46

10% \$ 797.55

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5860R

\$	7,177.91
----	-----------------

Special Nett

1 1SET PARKING AID	\$	Sm	700.00	X
2 1 BOOT FINISHER NUT L70Y	\$	nn	60.00	X
3 1SET REAR BUMPER CLIP	\$	nn	66.00	✓
4 1SET BUMPER BRACKET CTR CLIP	\$	nn	33.00	X
5 1SET BUMPER BRACKET SIDE CLIP RH RR	\$	nn	10.00	X
6 1SET BUMPER RETAINER RH CLIP RR	\$	nn	20.00	X
7 1SET BUMPER BRACKET SIDE CLIP LH RR	\$	nn	10.00	X
8 1SET BUMPER RETAINER CLIP LH RR	\$	nn	20.00	X
9 1SET BUMPER LOWER REAR RIVET	\$	nn	22.00	X
10 1SET BUMPER LOWER REAR CLIP	\$	nn	66.00	✓
11 1 EXHAUST MOUNTING REAR	\$	Sm	17.82	X
12 1 REAR NUMBER PLATE WITH HOLDER	\$	Sm	120.00	X
13 1 REAR BOOT STICKER 'Trans-cab'	\$	nn	80.00	30sm ✓
14 1 REAR BOOT STICKER '6555-3333'	\$	nn	80.00	30sm
TOTAL	\$		1,304.82	
TOTAL PARTS	\$		8,482.73	

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	660k
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00	600l
To Rust-Proofing Of The Affected Areas.	\$	170.00	60l
To reinstall rear bumper parking sensor.	\$	170.00	60l
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	60l
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	60l

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5860R

To check steering geometry and computer wheel alignment

\$ *na* 220.00 *X*

To Check Electrical Lighting Concerned.

\$ 170.00 *201*

TOTAL \$ 7,070.00

Over All Total \$ 22,730.65

(LUMP SUM)

Repair Days

20 DAYS

5 days

For Official Use

Prepared By : _____
(Accident Dept)

Verify By : _____
(Accident Workshop)

Checked By : _____
(Finance Dept)

LK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____