



SKODA Commercial Vehicles

Quotation

Non binding - Preview

Company

AIG ASIA PACIFIC INSURANCE P/L
78 Shenton Way
#07-16 AIG Building
Singapore 079120

Customer Details:

Mr
WANG
HUAWEI
353C EAST COAST ROAD
SINGAPORE 429096

Page

1/2

Document no.

Document date 23-11-2020
Customer no. 5211043795
Customer GST-ID 201009404M
Dealer 30001
Job order number 2020031732/ 1
Job order date 23-11-2020
Service Advisor CHARMAINE KONG

License plate	Model code	First registration	VIN	Model	Mileage
SMT5699S	NS7RKCS1	23-07-2020	TMBKC9NS7L8054691	Kodiat Sportline 1.4 I TSI 110kW -WCMY20	8,310

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
	Diagnostic and Programming	1	pcs.	480.00	#1	480.00	513.60
	Check Short Circuit / Harness Repair	1	pcs.	280.00	#1	280.00	299.60
565827023B	Unbekannt (BOOTLID) <i>3bt</i>	1	pcs.	2,894.14	#1	2,894.14	3,096.73
565853687G 041	Unbekannt (SKODA) <i>3rec</i>	1	pcs.	98.51	#1	98.51	105.41
565853687H 041	Unbekannt (KODIAQ) <i>3rec</i>	1	pcs.	98.51	#1	98.51	105.41
565807423	Bump Strip	1	pcs.	226.00	#1	226.00	241.82
565807421	Cover For (REAR BUMPER UPPER) <i>repair</i>	1	pcs.	1,740.00	#1	1,740.00	1,861.80
565807521G	Cover For (REAR BUMPER LOWER) <i>repair</i>	1	pcs.	571.00	#1	571.00	610.97
565807251A	Foam Reinf (REAR BUMPER FOAM) <i>3? x sue</i>	1	pcs.	129.00	#1	129.00	138.03
565919493C GRU	Sensor Bra <i>x sue</i>	1	pcs.	42.10	#1	42.10	45.05
565919491E	Sensor Bra	1	pcs.	42.10	#1	42.10	45.05
565919491D	Sensor Bra	1	pcs.	42.10	#1	42.10	45.05
565919492D	Sensor Bra	1	pcs.	42.10	#1	42.10	45.05
565919492E	Sensor Bra	1	pcs.	42.10	#1	42.10	45.05
565919494C GRU	Sensor Bra	1	pcs.	42.10	#1	42.10	45.05
D 822150A1	Bonding Agent For Plastic <i>x n</i>	1	pcs.	59.40	#1	59.40	63.56
D 180KU2A1	2k-Plastic Adhesive <i>x n</i>	1	pcs.	75.94	#1	75.94	81.26
5JJ945097A	Unbekannt (THIRD BRAKELIGHT) <i>3? x sue photo?</i>	1	pcs.	181.76	#1	181.76	194.48
D 169300M2	1k Window Adhesive <i>rec</i>	2	pcs.	49.51	#1	99.02	105.95
D 00920002	Primer <i>rec</i>	1	pcs.	25.74	#1	25.74	27.54
D 00950025	Applicator <i>rec</i>	2	pcs.	9.39	#1	18.78	20.09
D 181802M1	Activator For Precoated W <i>rec</i>	1	pcs.	23.77	#1	23.77	25.43
D 002000A2	Adhesive Remover <i>rec</i>	1	pcs.	114.78	#1	114.78	122.81
565807863	Retaining BUMPER CTR BRACKET <i>3? x sue</i>	1	pcs.	70.90	#1	70.90	75.86
WHT007341	Rivelled Cap Nut <i>rec</i>	4	pcs.	2.23	#1	8.92	9.54
	TRANSFER BOOT MECHANISM	1	pcs.	840.00	#1	840.00	898.80
	R&R REAR WINDSCREEN	1	pcs.	840.00	#1	840.00	898.80
	Spray Painting	4	pcs.	800.00	#1	3,200.00	3,424.00
	LABOUR	4	pcs.	840.00	#1	3,360.00	3,595.20
	REAR WATER LEAK TEST	1	pcs.	150.00	#1	150.00	160.50

Quotation valid till 30-11-2020

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#1	760.00	15,078.77	7%	1,108.71	15,838.77	16,947.48

SKODA Centre Singapore
Leng Kee Rd
Singapore 159104
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page 2/2

Company
AIG ASIA PACIFIC INSURANCE P/L
78 Shenton Way
#07-16 AIG Building
Singapore 079120

Customer Details:
Mr
WANG
HUAWEI
353C EAST COAST ROAD
SINGAPORE 429096

Document no. 23-11-2020
Document date 5211043795
Customer no. 201009404M
Customer GST-ID 30001
Dealer 2020031732/ 1
Job order number 23-11-2020
Job order date CHARMAINE KONG
Service Advisor

License plate SMT5699S	Model code NS7RKCS1	First registration 23-07-2020	VIN TMBKC9NS7L8054691	Model Kodiaq Sportline 1.4 I TSI 110kW -WCMY20	Mileage 8,310	
Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
Total	760.00	15,078.77		1,108.71	15,838.77	16,947.48

Customer

Service Advisor

-----VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).-----

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rahul
Hp 90010068
5 days
26/11/2020 @ 1610
Resurvey before paint