

CN MOTORS PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-41 Autobay@Kaki Bukit, Singapore 417883

Email: admin@cnmotorspl.com

Tel: 6509 5545 Fax: 6509 5567

UEN: 202026492W

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

20/11/2020

Accident date: 19/11/2020

Estimated repair cost for vehicle no: SJP6539X HONDA CIVIC 1.6L 5AT 09'

CHASSIS: JHMF D46209S 200763.

TP 111
Xiao Tong

S/n	Qty	Items	U/price	Amount
1	1	Front Bumper <i>Deland</i>		\$638.20 ✓
2	10	Front Bumper Clip <i>in</i>	\$6.50	\$65.00 ✓ 30
3	1	Front R/H Bumper Side Retainer <i>in</i>	\$25.00	\$25.00 ✓
4	1	Front Bumper Reinforcement <i>Neu</i>		\$377.90 X
5	1	Front R/H Bumper Fog Lamp Cover <i>above</i>		\$45.20 X
6	1	Front R/H Headlamp <i>cut</i>		\$1,299.80 750.40
7	1	Front R/H Headlamp Lower Bracket <i>Neu</i>		\$39.00 X
9	1	Front R/H Fender		\$450.80 X
11	1	Front R/H Fender Cowling		\$85.80 X
12	6	Front R/H Fender Cowling Clip <i>NP</i>	\$6.50	\$39.00 X
14	1	Front R/H Tyre <i>in</i>		\$380.00 X
15	1	Front R/H Rim <i>cut</i>		\$1,200.00 400(SN) X
Subtotal :-				\$4,645.70

1483.60

118688

S.N: 400

Labour charges

To check wiring	\$100.00	30
Towing fee	\$150.00	X
Tuff kote	\$150.00	X
Panel beating	630	\$1,000.00 200
Spray painting		\$1,000.00 400

Subtotal :- \$2,400.00

Total:- \$7,045.70

total: 2216.88

4/5: 1.7K

03 Days

1.7K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance company

Acknowledged by Repairer
Signature:
Date: