

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

RICHMOND CHAN JUN JIE
 BLK 730 JURONG WEST ST 72 #11-43
 SINGAPORE 640730

Contact : 88870730

TP China
Shirley

ESTIMATE

Repair Code : CLM15102

Date in : 23/11/2020

Vehicle Num. : SDK7373Y

Model : MITSUBISHI EVO 10 GSR 2.0 M

Chassis/Eng# : CZ4A0000751/4B11AS7288

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BOOTLID WEATHER STRIP <i>new</i>	1	155.00	155.00 <i>x</i>
REAR BUMPER <i>behind</i>	1	810.00	810.00 <i>✓</i>
REAR BUMPER LOWER LID <i>could</i>	1	348.00	348.00 <i>✓</i>
REAR BUMPER NUMBER PLATE LAMP BRACKET L/R <i>Best</i>	2	18.00	36.00 <i>✓</i>
REAR BUMPER NUMBER PLATE LAMP L/R <i>could</i>	2	39.00	78.00 <i>✓</i>
REAR BUMPER REFLECTOR L/R <i>could</i>	2	42.00	84.00 <i>✓</i>
REAR BUMPER REINFORCEMENT <i>new</i>	1	409.00	409.00 <i>x</i>
REAR BUMPER SIDE RETAINER L/R <i>new</i>	2	29.00	58.00 <i>✓</i>
REAR BUMPER TOP BRACKET <i>Best</i>	1	109.00	109.00 <i>✓</i>
REAR END PANEL <i>Regis</i>	1	506.00	506.00 <i>+</i>
REAR END PANEL INNER TOP GARNISH <i>behind</i>	1	149.00	149.00 <i>✓</i>
REAR TAILLAMP L/R <i>new</i>	2	332.00	664.00 <i>x</i>
Subtotal before discount			3,406.00
Percentage discount 10%			340.60
Sub-total 1			3,065.40
REAR BUMPER CLIPS - SET <i>new</i>	1	50.00	50.00 <i>30</i>
REAR BUMPER NUMBER PLATE <i>could</i>	1	120.00	120.00 <i>80</i>
REAR BUMPER NUMBER PLATE GARNISH <i>new</i>	1	50.00	50.00 <i>x</i>

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

RICHMOND CHAN JUN JIE
 BLK 730 JURONG WEST ST 72 #11-43
 SINGAPORE 640730

Contact : 88870730

ESTIMATE

Repair Code : CLM15102
 Date in : 23/11/2020
 Vehicle Num. : SDK7373Y
 Model : MITSUBISHI EVO 10 GSR 2.0 M
 Chassis/Eng# : CZ4A0000751/4B11AS7288

REAR BUMPER REVERSE CAMERA <i>Dengd</i>	<i>500</i> 1	800.00	800.00 <i>380</i>
REAR END PANEL INNER TOP GARNISH CLIPS - SET <i>me</i>	1	30.00	30.00 <i>10</i>
Subtotal before discount			1,050.00
Percentage discount 0%			0.00
Sub-total 2			1,050.00
Parts-total			4,115.40

LABOUR

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.		100.00	<i>80</i>
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	<i>960</i>	120.00	<i>40</i>
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.		800.00	<i>400</i>
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.		700.00	<i>400</i>
To apply anti-rust chemical on repaired and replaced panel.		80.00	<i>40</i>
Labour Total			1,800.00
Parts & Labour Total			5,915.40

*** This is a computer-generated document which requires no signature.***

page 2

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Adrian Lj
h/s 24/11/20.
04 days,
total: 2964.80
h/s: 2.3k ✓