

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

23-Nov-20

ESTIMATE REPAIR BILL FOR HYUNDAI I30(A) WAGON REGN NO: SHD 1439 X

2 pcs	Rear n/s & o/s tail lamp @ \$321.30	X NN	\$	642.60
2 pcs	Rear n/s & o/s reflector @ \$295.10	X NN	\$	590.20
1 pc	End panel	X NN	\$	853.85
1 pc	Tailgate	OR	\$	2,292.30
1 pc	Tailgate lower garnish	OR	\$	362.61
1 pc	Tailgate lock	X NN	\$	216.48
1 pc	Tailgate striker	X NN	\$	36.50
2 pcs	Tailgate hinge @ \$28.50	X NN	\$	57.00
1 pc	Tailgate weatherstrip	X NN	\$	276.98
2 pcs	Rear license plate lamp @ \$18.60	X NN	\$	37.20
1 pc	Rear wiper motor	X NN	\$	261.40
1 pc	Rear wiper arm	X NN	\$	30.60
1 pc	Emblem I30	OR	\$	27.80
1 pc	Emblem CRDI	OR	\$	29.40
1 pc	Emblem Hyundai	OR	\$	29.40
1 pc	Rear bumper	OR	\$	811.11
1 pc	Rear bumper sponge	1 X NN	\$	79.20
1 pc	Rear bumper reinforcement	1 X NN	\$	815.64
1 pc	Rear bumper reinforcement centre	1 X NN	\$	79.20
2 pcs	Rear bumper n/s & o/s side bracket @ \$52.20	X NN	\$	104.40
2 pcs	Rear bumper n/s & o/s reflector @ \$107.50	X NN	\$	215.00
				<hr/>
				\$ 7,848.87
				<hr/>
				Less 20%
				\$ 1,569.77
				<hr/>
				\$ 6,279.10

S/NETT

1 set	Rear bumper clips	OR	\$	48.00	30
1 set	Reverse sensor	OR	\$	280.00	200
1 set	Tailgate stickers	OR	\$	100.00	80
1 set	Tailgate lower garnish clips	OR	\$	38.00	20
1 pc	Rear no. plate with casing	X NN	\$	50.00	
1 pc	Sealant	OR	\$	50.00	20

23-Nov-20

ESTIMATE REPAIR BILL FOR HYUNDAI I30(A) WAGON REGN NO: SHD 1439 X

Sundry	\$	50.00	20
To dismantle and replace reverse sensor and test system	\$	80.00	30
To replace/refit the new rear windscreen glass into new shell tailgate	\$	120.00	/
To dismantle and refit the inner components of the tailgate into new tailgate, test wiper motor and water etc	\$	120.00	30
To labour charge for dismantle and renew the accident damaged parts. To heat/cut and weld on the end panel. Including to knock-out, straighten, repair, reshape of the same, etc	\$	800.00	499
To putty and spray painting on the rear bumper, tailgate, tailgate lower garnish, end panel,	\$	800.00	499
To apply rustproofing on the repaired and replaced panels	\$	150.00	30
Total	\$	8,965.10	

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Steve (LKK) WA PrL
24/11/20, 10.30am
3 dyl
L/S
My AL SLy

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary (if any) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: