



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO20012939/Ktd3e2	
			Date: 04/01/2021	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YN 6754Z	Veh. Inspected	FBL 9271M	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD2003430/RUC	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	24/11/2020	
2. Vehicle Particulars & Condition				
Make & Model	YAMAHA TRICITY (A)	c.c	155	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	MLESG381000056614	Colour	BLUE	
Odometer	115741 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	80/90 R14	MICHELIN	5 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	130/70 R13	MICHELIN	6 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	28/09/2020	Inspection Date	25/11/2020	
Survey held at	GA MOTOR BLK 32 SIN MING DRIVE #01-331 SINGAPORE 575706			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	