

'Think One Autocare Pte Ltd
No:60 Jalan Lam Huat #02-32 Carros Centre
Singapore 737869

ESTIMATE

DATE 20.11.2020

VEHICLE NO: YP8278H NISSAN UD JNCLCF1ASJU

No	Qty	DESCRIPTION	AMOUNT S\$
1	1	FRONT BUMPER ASSY <i>X R</i>	3,620.00 <i>X</i>
2	1	FRONT BUMPER RE-INFORCEMENT <i>X SVC</i>	1,855.00 <i>X</i>
3	2	HEADLAMP ASSY LH <i>X SVC</i>	2,188.00 <i>X</i>
			<u>\$ 7,663.00</u>
LESS 10%			<u>\$ 766.30</u>
			<u>\$ 6,896.70</u>

LABOUR & MISCELLANEOUS:

AMOUNT S\$

1	To remove damaged body parts with all necessary components/attachments apply hot-works where necessary repair, reshape body dented panels in accordance with factory specifications replace new parts refit and align into position refit all necessary components/attachments	800.00 <i>500</i>
2	To spray paint replaced/repared body parts inclusive of preparatory works and painting materials	800.00 <i>500</i>
3	To conduct headlamp alignment	30.00
		<u>\$ 1,630.00</u>

Repair 2 days

P/P

After pain photo

See pin (446)

01/12/2020

TP with photo

*500
500
1,000*

*PIP
\$1,000*

2 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: