# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: India International Insurance Pte Ltd

> 64 Cecil Street #04-00 IOB Building Singapore 049711

From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Priya Date: 25 Nov 2020

## **Preliminary Advice**

Vehicle No : GBK3085D Accident Date : 22/11/2020

: D19MFL0005549 Make : NISSAN NV350 Policy No.

**Assignment Date** : 24/11/2020 **Excess** : S\$0.00 Date of Inspection : 24/11/2020 Est. Duration of Repair : 14

Inspection At : Efficient Motor & Engineering Works Pte Ltd (HQ)

56 Loyang Way #06-07, Loyang Enterprise Building

Singapore 508775

### Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	26,966.10
Revised Amount	:S\$	17,866.50
Check Items (Estimated)	:S\$	1,031.80
Total	:S\$	18,898.30

Lump Sum Repair :S\$

#### **Total Loss Consideration**

New for Old Value :S\$

Pre-Accident Value :S\$ 72,000.00 COE / PARF Rebate 23,379.00 :S\$

Salvage Value :S\$

Margin for Repair :S\$ 48,621.00

### Remarks

( X	( )	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
(	)	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
(	)	Other comments :