

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jasmine Lok Kheng Kwei

Date: 08 Dec 2020

Preliminary Advice

Insured Vehicle No	: SJZ3443E		
TP Vehicle No	: SKH5602H	Accident Date	: 24/11/2020
Make	: HONDA CIVIC	Assignment Date	: 24/11/2020
Date of Inspection	: 24/11/2020	Est. Duration of Repair	: 4
Inspection At	: JWG INTERNATIONAL PTE LTD (HQ) BLK 10, ANG MO KIO IND PARK 2A,, #03-08 AMK AUTOPOINT SINGAPORE 568047		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,601.64
Revised Amount	:S\$	4,636.88
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,636.88
 Lump Sum Repair	 :S\$	 3,700.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- ☐ The vehicle is economical for repair
☐ The vehicle is not economical for repair
☐ Part-by-Part repair
☒ Lump Sum repair

☒ The above survey was conducted on a 'without prejudice' basis.