



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0898/2020/NS
DATE : 21-Nov-20
WIP : 58503

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MR KAN YEU FONG (JIAN YAO FENG)
ADDRESS : BLK 55 TEBAN GARDENS ROAD
SINGAPORE 600055
TELEPHONE : HP +65 93883371
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1900261266
VEHICLE NO : SMR 3066 S
MODEL CODE : AUDI A3 SEDAN 1.0 TFSI 8V
MODEL YEAR : 27/12/2019
ENGINE NO : CHZ C31903
CHASSIS NO : WAUZZZ8V1KA109725
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 20-Nov-20
PLACE OF ACCIDENT : AYER RAJAH EXPRESSWAY



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMR 3066 S

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE.	S/N \$ 280.00	✓
2	TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS.	S/N \$ 280.00	X
3	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,100.00	500 ✓
4	TO RESPRAY REAR BUMPER, HINGES AND REAR LID.	\$ 2,200.00	500 1100 ✓
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 5,052.00	



PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO.

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
1 REAR BUMPER <i>rebrand</i>		\$ 1,944.00	✓ 1555.20
2 REAR BUMPER FIXING PARTS <i>not a</i>		\$ 191.00	+
3 REAR BUMPER GUIDE SECTION - LH/RH <i>2</i>	2	\$ 32.00	+
4 REAR BUMPER LOCKING MECHANISM <i>2</i>	2	\$ 59.00	+
5 REAR BUMPER SPOILER <i>at</i>		\$ 234.00	✓ 187.20
6 REAR LIGHT REFLECTOR - LH/RH <i>not a</i>	2	\$ 82.00	X
7 LED TAIL LIGHT - LH <i>not a</i>		\$ 867.00	+
8 TAIL LIGHT TRIM - LH <i>not a</i>		\$ 30.00	+
9 LED LICENSE PLATE LIGHT <i>2</i>	2	\$ 197.00	+
10 LED TAIL LIGHT - RH <i>not a</i>		\$ 867.00	+
11 TAIL LIGHT TRIM - RH		\$ 30.00	+
12 REAR REINFORCEMENT BEAM <i>not a</i>		\$ 565.00	+
13 REAR BUMPER BRACKET - LH <i>2</i>		\$ 27.00	+
14 REAR BUMPER BRACKET - RH <i>not a</i>		\$ 28.00	+
15 REAR PARKING AID SENSOR - LH/RH <i>not a</i>	2	\$ 484.00	+
16 REAR PARKING AID SEAL RING <i>not a</i>	4	\$ 14.00	+
17 REAR LID <i>Repair</i>		\$ 2,564.00	+
18 REAR LID ATTACHMENT PARTS <i>2</i>		\$ 291.00	+
19 REAR LID HINGE - LH/RH <i>not a</i>	2	\$ 506.00	+
20 REAR LID FLAP GASKET		\$ 203.00	+
SUB TOTAL SPARE PARTS	:	\$ 9,215.00	



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO.

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
21 PACKING ADHESIVE		\$ 18.00	✓ 14.40
22 AUDI EMBLEM		\$ 122.00	✓ 97.60
23 A3 INSCRIPTION		\$ 95.00	✓ 75.36
24 REAR CROSS PANEL TRIM		\$ 153.00	+
25 REAR NO PLATE	S/N	\$ 60.00	+
26 SUNDRIES		\$ 300.00	→ X
TOTAL SPARE PARTS	:	\$ 9,963.00	
TOTAL LABOUR CHARGES	:	\$ 5,052.00	
GRAND TOTAL	:	\$ 15,015.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

PA/OD/0898/2020/NS

Date

23/12/2020

Service Advisor

Raymond Ting

Pages

1 of 1

Regn No

SMR 3066 S

Model No

AUDI A3 SEDAN 1.0 TFSI 8V

Quantity	Description	Unit Price	Amount
<u>Labours</u>			
1	TO RECOAT CERAMIC COATING	\$ 688.00	✓ 850
TOTAL		\$ 688.00	

For Premium Automobiles Pte Ltd

Authorised Signature

Adrian Ling
H.S.



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : Adrian King
SURVEYED DATE : 24/11/20
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : Not Authorised, 0A Days

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT