



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD	INV No.	AC2106385
3 ANSON ROAD #16-00	INV Date	13/09/2021
SPRINGLEAF TOWER	Reference	CC3/CTI20012961/Kea3q2
SINGAPORE 079909	Code	CTI

### PROFESSIONAL SERVICE FEE

Vehicle No.	SHD 482B
Insured Veh.	SKB 9178X
Claim No.	SNM20D204500/C02
Policy No.	DMPCSNA00003842001
Accident Date	20/11/2020
Inspection Date	23/11/2020

Description	Total
Survey Inspection	350.00
Digital Photographs	
Transportation	
<b>Subtotal</b>	<b>350.00</b>
<b>GST (7%)</b>	<b>24.50</b>
<b>Grand Total</b>	<b>374.50</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**LKM**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD  
3 ANSON ROAD #16-00  
SPRINGLEAF TOWERSINGAPORE 079909

Ref: CC3/CTI20012961/Kea3q2

Date: 13/09/2021

Code: CTI

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	SKB 9178X	<b>Veh. Inspected</b>	SHD 482B
<b>Policy No.</b>	DMPCSNA00003842001	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	SNM20D204500/C02	<b>Excess (\$)</b>	0.00
<b>Assign From</b>		<b>Assign Date</b>	23/11/2020

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	RENAULT LATITUDE (A)	<b>c.c</b>	1995
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2017
<b>Chassis No.</b>	VF1ABL15AUC283292	<b>Colour</b>	METALLIC WHITE/RED
<b>Odometer</b>	228930 KM	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	NIL
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	215/60 R16	SAILUN	8 mm
<b>L/H Front Tyre</b>	215/60 R16	SAILUN	8 mm
<b>R/H Rear Tyre</b>	215/60 R16	SAILUN	8 mm
<b>L/H Rear Tyre</b>	215/60 R16	SAILUN	8 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.  
DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	20/11/2020	<b>Inspection Date</b>	23/11/2020
<b>Survey held at</b>	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	<b>2 Working Days</b>
-------------------------------------	-----------------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 482B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	DOOR PANEL REAR RH	TO REPAIR SEE LABOUR	2,844.66	-
1	DOOR REGULATOR REAR RH	SERVICEABLE	758.10	-
1	DOOR REGULATOR MOTOR REAR RH	SERVICEABLE	450.60	-
1	DOOR PANEL FRT RH	TO REPAIR SEE LABOUR	2,844.66	-
1	DOOR REGULATOR FRT RH	SERVICEABLE	505.19	-
1	DOOR REGULATOR MOTOR FRT RH	SERVICEABLE	796.46	-
1	DOOR REGULATOR GUIDE FRT RH	SERVICEABLE	120.97	-
1	FENDER PANEL REAR RH	TO REPAIR SEE LABOUR	1,933.20	-
1	FENDER BRACKET LOWER RH	SERVICEABLE	11.80	-
1	WHEELARCH REAR RH	SERVICEABLE	275.40	-
1	ROCKER PANEL OUTER RH	TO REPAIR SEE LABOUR	1,184.99	-
	LESS 10% DISCOUNT		-1,172.60	-
			10,553.43	-
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET FENDER SCREW (SN)	NOT NECESSARY	60.00	-
1	SET CLIP ,FRONT FENDER LINER (SN)	NOT NECESSARY	65.00	-
1	BUMPER CLIP FRT (SN)	NOT NECESSARY	90.00	-
1	BUMPER RETAINER CLIP FRT (SN)	NOT NECESSARY	75.00	-
1	WHEELARCH CLIP FRT (SN)	NOT NECESSARY	75.00	-
1	DOOR FINISHER CLIP KIT FRT RH (SN)	NOT NECESSARY	90.00	-
1	DOOR MOULDING CLIP L70Y (SN)	NOT NECESSARY	80.00	-
1	DOOR MOULDING SCREW L70Y (SN)	NOT NECESSARY	65.00	-
1	DOOR CASING CLIP (SN)	NOT NECESSARY	85.00	-
1	DOOR STICKER 'TRANS-CAB' (SN)	NECESSARY	100.00	60.00
1	DOOR STICKER '6555-3333' (SN)	NECESSARY	100.00	60.00
1	DOOR STICKER 'CLASSIC' (SN)	NECESSARY	100.00	15.00
			985.00	135.00



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>LABOUR</b>			
	TOWING FEES.	NOT NECESSARY	170.00	-
	TO TRANSFER OF DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	300.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF DOOR PANEL REAR RH,DOOR PANEL FRT RH ,FENDER PANEL REAR RH AND ROCKER PANEL OUTER RH .		1,400.00	200.00
	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS .	NOT NECESSARY	240.00	-
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION .		1,400.00	440.00
	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	15.00
			4,450.00	655.00
	<b>GRAND TOTAL</b>		<b>15,988.43</b>	<b>790.00</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>790.00</b>

Report Ref No. CC3/CTI20012961/Kea3q2

**KONG SENG CHEONG**

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## PHOTOGRAPHS FOR VEHICLE NO. SHD 482B

## INSPECTION





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R



