

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD482B**

AAD2011-113

*Not Authored*

*1/Sup B*

Vehicle No.:  
 Chassis No.:  
 Vehicle Make:  
 Vehicle Model: **23 NOV 2020**  
 Date of Accident :  
 Third Party Insurer :  
 Date of Registration:

**SHD482B**  
 VF1ABL15AUC283292  
 RENAULT  
 LATTITUDE  
 19/11/2020  
**CHINA**  
 07/08/2017

- |   | <b>PART</b>                  |
|---|------------------------------|
| 1 | DOOR PANEL REAR RH           |
| 1 | DOOR REGULATOR REAR RH       |
| 1 | DOOR REGULATOR MOTOR REAR RH |
| 1 | DOOR PANEL FRT RH            |
| 1 | DOOR REGULATOR FRT RH        |
| 1 | DOOR REGULATOR MOTOR FRT RH  |
| 1 | DOOR REGULATOR GUIDE FRT RH  |
| 1 | FENDER PANEL REAR RH         |
| 1 | FENDER BRACKET LOWER RH      |
| 1 | WHEELARCH REAR RH            |
| 1 | ROCKER PANEL OUTER RH        |

|              | <b>LIST</b> |                  |
|--------------|-------------|------------------|
| \$           | R           | 2,844.66         |
| \$           | SL          | 758.10           |
| \$           | SL          | 450.60           |
| \$           | R           | 2,844.66         |
| \$           | SL          | 505.19           |
| \$           | SL          | 796.46           |
| \$           | SL          | 120.97           |
| \$           | R           | 1,933.20         |
| \$           | SL          | 11.80            |
| \$           | SL          | 275.40           |
| \$           | R           | 1,184.99         |
| <hr/>        |             |                  |
| <b>TOTAL</b> | <b>\$</b>   | <b>11,726.03</b> |
| <b>10%</b>   | <b>\$</b>   | <b>1,172.60</b>  |
|              | <b>\$</b>   | <b>10,553.43</b> |

- |      | <b>Special Nett</b>           |
|------|-------------------------------|
| 1SET | FENDER SCREW                  |
| 1SET | CLIP, FRONT FENDER LINER      |
| 1    | BUMPER CLIP FRT               |
| 1    | BUMPER RETAINER CLIP FRT      |
| 1    | WHEELARCH CLIP FRT            |
| 1    | DOOR FINISHER CLIP KIT FRT RH |
| 1    | DOOR MOULDING CLIP L70Y       |
| 1    | DOOR MOULDING SCREW L70Y      |
| 1    | DOOR CASING CLIP              |
| 1    | DOOR STICKER "TRANSCAB"       |
| 1    | DOOR STICKER "6555-3333"      |
| 1    | DOOR STICKER "CLASSIC"        |

|              |           |               |
|--------------|-----------|---------------|
| \$           | UN        | 60.00         |
| \$           | UN        | 65.00         |
| \$           | UN        | 90.00         |
| \$           | UN        | 75.00         |
| \$           | UN        | 75.00         |
| \$           | UN        | 90.00         |
| \$           | UN        | 80.00         |
| \$           | UN        | 65.00         |
| \$           | UN        | 85.00         |
| \$           | UN        | 100.00        |
| \$           | UN        | 100.00        |
| \$           | UN        | 100.00        |
| <hr/>        |           |               |
| <b>TOTAL</b> | <b>\$</b> | <b>985.00</b> |

**Trans-cab Auto Services Pte Ltd**

AAD2011-113

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD482B

**TOTAL PARTS \$ 11,538.43**

**LABOUR**

|   |    |           |          |             |
|---|----|-----------|----------|-------------|
| Towing fees   | \$ | <i>nn</i> | 170.00   | X           |
| To transfer of door fittings, attachment and perform water seepage test.  | \$ | <i>nn</i> | 300.00   | X           |
| To check steering geometry and computer wheel alignment   | \$ | <i>h</i>  | 220.00   | X           |
| To remove and refit interior fittings, trimings, garnish, fittings and others, to enable repair.                          | \$ | <i>h</i>  | 380.00   | X           |
| Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same | \$ |           | 1,400.00 | <i>2001</i> |
| To rust-proofing and apply undercoat of the affected areas.   | \$ | <i>h</i>  | 240.00   | X           |
| Putty and spray painting of the affected portion.   | \$ |           | 1,400.00 | <i>4401</i> |
| To transfer of tire, rim and on wheel balancing.  | \$ | <i>h</i>  | 170.00   | X           |
| To Check Electrical Lighting Concerned.   | \$ |           | 170.00   | <i>151</i>  |

**TOTAL \$ 4,450.00**

**Over All Total \$ 15,988.43**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- No illegal modification(s) is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

**For Official Use**

Acknowledged by Repairer  
Signature:  
Date:

**LUMP SUM (REPAIR DAY)**

*20 DAYS*  
*2 days*