

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63

Singapore 569111

Co./GST Reg. No. 201019626G

Tel No. : 6287 6666 Fax No. : 6257 1330

SHD62E**AAD2011-096***Not Authorised**83521-04*

L/S

\$2800.00

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHD62E

WDD2120012B222270

MERCEDES BENZ

E 220 BLUETEC

17/11/2020

AIG

16/12/2015

PART

- | | | |
|----|---|--|
| 1 | 1 | Front Bumper |
| 2 | 1 | Front Bumper Reinforcement |
| 3 | 1 | Front Bumper Lower Grille Carrier |
| 4 | 1 | Front Bumper Inner Sponge Absorber |
| 5 | 1 | Front Bumper Side Support Bracket |
| 6 | 1 | Front Bumper Reinforcement Bracket |
| 7 | 1 | Front Bumper Fog Lamp Grille RH |
| 8 | 1 | Front Bumper Fog Lamp Grille Cover Area LH |
| 9 | 1 | Front Bumper Grille Cover Moulding LH |
| 10 | 1 | Front Headlamp RH |
| 11 | 1 | Headlamp Control Unit |
| 12 | 1 | Front Headlamp Panel RH |

LIST

\$	1,417.44	}	X
\$	569.72		
\$	125.10		
\$	147.37		
\$	57.83		
\$	305.34		
\$	50.70		
\$	33.48		
\$	105.66		
\$	3,501.15		
\$	1,013.59		X
\$	275.80		X
TOTAL \$	7,603.18		
10% \$	760.32		
\$	6,842.86		

Special Nett

- | | |
|---|---|
| 1 | 1SET FRONT BUMPER CLIP |
| 2 | 1SET Front Bumper Inner Frame Clip LH |
| 3 | 1SET Front Bumper Inner Frame Metal Clip LH |
| 4 | 1 Front Bumper Center Air Grille Clip |
| 5 | 1 Front Bumper Retainer Clip |
| 6 | 1 Front Bumper Rivet |
| 7 | 1 Front Bumper Fog Lamp Grille Clip |

\$	100.00	}	X
\$	90.00		
\$	60.00		
\$	70.00		
\$	80.00		
\$	90.00		
\$	65.00		
TOTAL \$	555.00		

Trans-cab Auto Services Pte Ltd

AAD2011-096

No. 2 Ang Mo Kio Street 63

Singapore 569111

Co./GST Reg. No. 201019626G

Tel No. : 6287 6666 Fax No. : 6257 1330

SHD62E

GRAND TOTAL \$ 7,397.86**LABOUR**To Transfer Of Bumper Fittings, Attachment And
Perform Water Seepage Test.

\$ ~ 170.00 X

Panel Beating, Knocking And Straightening The
Necessary Portion, Remove And Renewal Of Parts,
Adjust And Realign The Same

\$ 8,500.00 1001

Putty And Spray Painting Of The Affected Portion.

\$ 8,500.00 2501

To Remove And Refit Interior Fittings, Trimings,
Garnish, Fittings And Other, to Enable Repair.

\$ ~ 380.00 X

To Rust-Proofing Of The Affected Areas.

\$ 170.00 X

To Check Electrical Lighting Concerned.

\$ 170.00 201

To Transfer Of Bootlid Fittings, Attachments And
Perform Water Seepage Test.

\$ 170.00 X

To rust-proofing of the affected areas.

\$ 170.00 X

To check steering geometry and computer wheel
alignment

\$ 220.00 X

Labour charge to mount and dismount vehicle on jig
bench, to facilitate repair.

\$ 380.00 X

TOTAL \$ 18,830.00**Over all total \$ 26,227.86****(LUMP SUM) Repair Days****25 DAYS****1 day**LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: