VEHICLE NO

SH9647H

MAKE

. HYLINDALIONIQ G2

/CHIANG /AIG

ODEL	: HYUNDAI IONIQ G2 Parts Description/ Labour	Туре	Unit Price	Amount
Qty	FRONT BUMPER COVER / 6 LIT			\$418.30
	IFRONT BUMPER COVER / # 5			\$93.45
	FRONT BUMPER GRILLE RH			\$642.50
1	FRONT DAYLIGHT RH X			\$35.00
	FRONT BUMPER BRACKET RH			\$1,993.65
	HEADLAMP ASSY RH	*		\$949.30
	HEAD SUPPORT PANEL X			\$588.80
1	FRONT RH FENDER ~ 00	10, 100		\$164.70
,	FRONT FENDER SHIELDRLH X	a 0 g		
1	FENDER EMBLEM BLUE -DRIVE / // C			\$26.60
1	FRONT RH WHEEL COVER / CVT			\$346.40
•	REAR BUMPER COVER 📈 🖟		(\$459.40
1	REAR BUMPER CENTRE MOULDING / CRU		0.0	\$451.25
1	REAR BUMPER REINFORCEMENT X			\$394.80
	REAR BUMPER CLIPS X	* ,		\$22.00
10	SUB TOTAL			\$6,586.1
W	20.00%			\$1,317.2
	DISCOUNTED TOTAL			\$5,268.9
1	REVERSE SENSOR X			\$180.00
1	REAR NUMBER PLATE W/HOLDER \diagup $\int \!$			\$50.0
				\$230.0
	Labour Charge	1.71	./	11
	Panel Beating FRONT/REAR		0	\$800.0
	Spray painting FRONT/REAR			\$800.0
	Check Lighting		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	\$60.0
	Remove/refix reverse sensor			\$60.0
	Tuff coating			30 \$90.0
	Remove/refix A/c condeser & charge gas		L A S	X \$120.0
	TOTAL LABOUR			\$1,930.0
	TOTAL DADOOR			1
	ESTIMATE TOTAL			\$7,428.
	Have CIVXI III			
	Stere (LKK) hu p			
	24/11/po,	4.10		
LVK Auto	•	, '		
the Repair	Consultants hence notify are of the following:)		
 To resurve 	before after spray painting			20
To display as Pads prices	amaged part(s) during resurvey			
Third party si	are subject to confirmation urvey is on a "Without Prejudice" basis	b. 1		
ivo illegal nio	dification(s) is allowed	10 C		
 Supplementa 	ry item(s) must be resurveyed and	"	41	
	nal approval from Insurance Company		Jana	
Acknowledge	by Repairer			
Signature:		,		

be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

MFORTDELGRO ENGINEERING

member of COMFORTDELGRQ

ComfortDelGro Engineering Pte Ltd

205 Braddek Road Singapore 579701 Maintine + 65 6383 5280 Facaintile + 85 5280 9755


Workshops
59 Loyang Orive Singapore 508959
383 Sir Ming Drive Singapore 513717
45 Parktan Ruad Singapore 513717
320 Jun Prod 1 Singapore 513717
24 - 11 2020 09: 33 Page: 1

Team: ARC Repair TP(CLSO)1	JOB CARD	Sales Order:	JC NO::305435290
Team: ARC Repair 1P(CLSO)1		REGN NO.: SH 9647H	MILEAGE
7010045	COMFORT TRANSPORTATION PTE LTD	MAKE: HYUNDAI	FUEL E1/2
DORESS 383 SIN MING DRIVE Singapore SINGAPORE 575717		MODEL IONIQ(G2) 21	DATE/TIME IN . 11.2020 13:15
EL (R) 65508755 (O)		YR OF MANU. 08.11.2018	TARGET DATE
(P)	CHASSIS CODE KMHC851CVKU115143	COMPLETION DATE/TIME	
HISCOUNT CARD NO.		The second section of the second second section of the second sec	Lander of the control

JOB DESCRIPTION

Accident Date: 21.11.2020 NATURE: 3P 21.11.2020

LABOR CODE



	REAR REAR
HECKED & PASSED OUT BY:	
SERVICE ADVISOR	CUSTOMER'S SIGNATURE
owledgement Slip	Exit Pass
: o.: o No.: SH 9647H CHIANG	Vehicle No.: SH 9647H
of Service Advisor Signature/Date	Name of Service Advisor Date
of Service Advisor Signature/Date eturned to Service Reception upon collection	To be kept by Security Guard