



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2100044

3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909

INV Date 05/01/2021  
Reference CC3/CTI20012967/Ees3q2  
Code CTI

### PROFESSIONAL SERVICE FEE

Vehicle No. SHB 8073G  
Insured Veh. GBG 2819G  
Claim No. SNM20D204606  
Policy No. DMCVSNW00053202002  
Accident Date 24/11/2020  
Inspection Date 24/11/2020

Description	Total
Third Party Express Settlement	400.00
<b>Subtotal</b>	<b>400.00</b>
<b>GST (7%)</b>	<b>28.00</b>
<b>Grand Total</b>	<b>428.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**LKM**



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC3/CTI20012967/Ees3q2 Date: 05/01/2021 Code: CTI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	GBG 2819G	Veh. Inspected	SHB 8073G	
Policy No.	DMCVSNW00053202002	Coverage (\$)	0.00	
Claim No.	SNM20D204606	Excess (\$)	0.00	
Assign From		Assign Date	24/11/2020	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	KIA OPTIMA	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	KNAGM414MF5658334	Colour	SILVER	
Odometer	472208 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	BRIDGESTONE	5 mm	
L/H Front Tyre	195/65 R15	BRIDGESTONE	5 mm	
R/H Rear Tyre	195/65 R15	BRIDGESTONE	5 mm	
L/H Rear Tyre	195/65 R15	BRIDGESTONE	5 mm	
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
Accident Date	24/11/2020	Inspection Date	24/11/2020	
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443			
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 8073G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR BUMPER	TO REPAIR SEE LABOUR	696.00	-
1	REAR BUMPER LOWER COVER	NOT NECESSARY	206.00	-
2	REAR BUMPER SIDE BRACKET O/S & N/S @\$29.00	NOT NECESSARY	58.00	-
1	REAR BUMPER INNER SPONGE	NOT NECESSARY	114.00	-
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	607.00	-
2	REAR BUMPER STAY O/S & N/S	NOT NECESSARY	108.00	-
2	REAR BUMPER REINFORCEMENT LOWER BRACKET @ \$18.00	NOT NECESSARY	36.00	-
2	REAR BUMPER REINFORCEMENT UPPER BRACKET @ \$18.00	NOT NECESSARY	36.00	-
2	REAR BUMPER REFLECTOR N/S & O/S @\$46.00	NOT NECESSARY	92.00	-
	LESS 10% DISCOUNT		-195.30	-
			1,757.70	-
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET REAR BUMPER CLIPS (SN)	NOT NECESSARY	48.00	-
1	SET END PANEL INNER GARNISH CLIPS (SN)	NOT NECESSARY	30.00	-
1	SET REVERSE SENSOR (SN)	NOT NECESSARY	280.00	-
1	REAR BUMPER PROTECTOR (SN)	NOT NECESSARY	80.00	-
1	BOOTLID STICKER (SN)	NECESSARY	80.00	80.00
1	SUNDRY (SN)	NOT NECESSARY	50.00	-
			568.00	80.00
<b><u>LABOUR</u></b>				
	TO DISMANTLE/REPLACE REVERSE SENSOR TO NEW BUMPER AND RESET TO THE SAME.	NOT NECESSARY	120.00	-
	TO DISMANTLE/REFIT THE INNER GARNISHES, INNER LININGS, INNER TRIMS, CUSHION SEAT, CARPET, ETC TO FACILITATE REPAIRS.	NOT NECESSARY	180.00	-
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS INCLUDING KNOCK-OUT, STRAIGHTEN, REPAIR, RESHAPE AND ADJUST OF THE END PANEL ETC. INCLUSIVE OF THE REPAIR OF REAR BUMPER.		600.00	200.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PUTTY AND SPRAY PAINTING ON REAR BUMPER,END PANEL,BOOT LID,BOOT LID LOWER GARNISH.	NOT NECESSARY	800.00	400.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.		80.00	-
			1,780.00	600.00
<b>GRAND TOTAL</b>			<b>4,105.70</b>	<b>680.00</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>680.00</b>

Report Ref No. CC3/CTI20012967/Ees3q2

**CHEN TSUE YEE**

**Automotive Assessor**

**HO LEONG CHUAN**

**Automotive Assessor**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHB 8073G

INSPECTION







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHB 8073G

RE-INSPECTION

