

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG: 200707743D GST REG: 200707743D

Stew (LKK)

Wu AL

24/11/20, 3pm

24-Nov-20

2 dgs, AL, L/S

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 8073 G

1 pc	Rear bumper X R	\$ 696.00
1 pc	Rear bumper lower cover X	\$ 206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00 X	\$ 58.00
1 pc	Rear bumper inner sponge X	\$ 114.00
1 pc	Rear bumper reinforcement X	\$ 607.00
2 pcs	Rear bumper stay o/s & n/s @ \$53.00 X	\$ 108.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00 X	\$ 36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00 X	\$ 36.00
2 pcs	Rear bumper reflector n/s & o/s @ \$46.00 X	\$ 92.00
		<hr/>
		\$ 1,953.00
Less 10%		\$ 195.30
		<hr/>
		\$ 1,757.70

S/NETT

1 set	Rear bumper clips X	\$ 48.00
1 set	End panel inner garnish clips X	\$ 30.00
1 set	Reverse sensor X	\$ 280.00
1 pc	Rear bumper protector X	\$ 80.00
Sundry		\$ 50.00 X
To dismantle / replace reverse sensor to new bumper and reset to the same		\$ 120.00 X
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.		\$ 180.00 X
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the end panel etc		\$ 600.00 200

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

To apply rustproofing on the repaired and replaced panels.

\$ 800.00	400
\$ 80.00	X
<hr/>	
\$ 4,025.70	

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

Acknowledged by Repairer

Signature:

Date: