

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle Number : SLV 7934B

Vehicle Model : MAZDA 3

Accident Date : 22.11.2020

Original Reg Date : 16.01.2018

Date :

23.11.2020

Chassis :

JM6BN24A8J0200941

TP Ins.

FIRST CAP

ESTIMATE

1	1 pc	Front Bumper		de	967.00
2	2 pcs	Front Bumper Side Retainers	RHX	38.00	LH-de 76.00
3	1 set	Front Bumper Clips		re	50.00
4	1 pc	Front Bumper Top Garnish		X	175.20
5	1 pc	Front Bumper Reinforcement		?	529.50
6	1 pc	Front Bumper Lower Grille		X	141.50
7	1 pc	Front Bumper Fog Lamp LED LH		?	369.00
8	1 pc	Front Bumper Fog Lamp Cover LH		cut	85.50
9	1 pc	Front Bumper Fog Lamp Chrome LH		?	72.00
10	1 pc	Front Grille		?	560.00
11	1 pc	Front Grille Badge		?	69.00
12	2 pcs	Front Grille Outer Chrome Moulding	RHX	149.00	LH-? 298.00
13	1 set	Front Grille Clip		?	30.00
14	1 pc	Headlamp (HID) LH		?	1,889.00
					5,311.70
Less 20%					1,062.34
					4,249.36

Labour charge

Panel Beating		400	900.00
Spray painting		500.	900.00
Check Wiring		30.	40.00
Anti rust		X	50.00

Tanpin 97495749
 WP' 24/11/2015
 Lum psur 04 days
 Repair after repair
 Tanpin C 11/11/2015

Less 20%

6,139.36

Lump sum

1,227.87

4,911.49

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: