



南方摩哆 Southern Motor

Business Reg. No: 234147/00L
Block 1006, Bukit Merah Lane 2. #01-10, Singapore 159762
Tel: 6273-0369 (3 Lines) Fax: 6274-6614

23rd November 2020

AIG Asia Pacific Insurance Pte Ltd

78 Shanton Way #07-16

AIG Building

Singapore (079120)

Dear Sirs,

RE: Cost of repair to Yamaha Super Tenere- FBK6017G

1pc of Handle Bar	S\$	235.00
1pc of Handle Guard		285.00
1pc of Centre Fairing		325.00
1pc of Engine Guard		380.00
1pc of Yamaha Rear Side Box Comp		2,400.00
		<hr/> 3,625.00
	Less 10%	362.50
	Nett	3,262.50
	Labor	160.00
		<hr/> <u>\$3,422.50</u>



Yours Faithfully,
Southern Motor

Date: 23rd November 2020

Southern Motor
Blk 1006 Bukit Merah Lane 2
#01-10
Singapore 159762

Motor Claims Department
AIG Asia Pacific Insurance Pte Ltd
78 Shanton Way #07-16
AIG Building
Singapore 079120

Dear Sirs,

RE: ACCIDENT INVOLING FBK6017G AND SJH5343S ALONG
Orchard Road ON 17-11-2020 AT 21:10PM

Please be informed that the above-said motorcycle bearing registration no: FBK6017G was seriously damaged during the above-said accident and was beyond economic repair.

Kindly arrange for your surveyor to survey the above-mentioned motorcycle at Blk 1006, Bukit Merah Lane 2 #01-10 Singapore 159762. (Tel:62730369)

Thanking you in advance,

Yours Faithfully,



Enc.