



南方摩哆 Southern Motor


Business Reg. No: 234147/00L
Block 1006, Bukit Merah Lane 2. #01-10, Singapore 159762
Tel: 6273-0369 (3 Lines) Fax: 6274-6614

23rd November 2020
AIG Asia Pacific Insurance Pte Ltd
78 Shanton Way #07-16
AIG Building
Singapore (079120)

Dear Sirs,

RE: Cost of repair to Yamaha Super Tenere- FBK6017G

1pc of Handle Bar ?	S\$	235.00
1pc of Handle Guard <i>SCA</i> /		285.00
1pc of Centre Fairing <i>SCA</i> /		325.00
1pc of Engine Guard <i>SCA</i> /		380.00
1pc of Yamaha Rear Side Box Comp <i>bt</i> /		2,400.00
		3,625.00
	Less 10%	362.50
	Nett	3,262.50
	Labor	160.00
		<u>\$3,422.50</u>



Yours Faithfully,
Southern Motor

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul
Hp 90010068

2 days
25/11/2020
@1405

4/5

Reg after rep ✓