

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SJB 2582U

TP/AIG

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

WS Ref: TP/AIG

Claim Type: Third Party

Accident Date: 18/11/2020

TP Veh Reg No: SGP6876H

Estimate No: ES2190087/YISHUN

Date: 02 Feb 2021

Policy No: MP313491

Veh Reg No: SJB2582U

Make/Model: NISSAN NISSAN
PULSAR 1.2 DIG-T CVT

Chassis No: VSKDDAC13U0109741

Engine No: HRA2463241A

Reg. Date: 18/09/2017

Estimate Repair Cost to Vehicle No :SJB2582U

Description	U/Price	Quantity	List Price	Amount
			S\$	S\$
Net Price				
1 REAR BUMPER	870.00	1 PC	870.00	✓
2 REAR BUMPER RH SIDE RETAINER	75.00	1 PC	75.00	✓
3 REAR BUMPER CLIPS	3.00	6 PCS	18.00	✓
			963.00	
		Less 10%	96.30	866.70
Labour				
4 REMOVE & REFIX REAR BUMPER ASSY, REAR BUMPER LOWER SKIRT, REVERSE SENSOR, REALIGN & RESET REVERSE SENSOR, KNOCK & REPAIR REAR RH FENDER	380.00	1 LA	380.00	260
5 PUTTY & RESPRAY ON REAR BUMPER, REAR RH FENDER	500.00	1 LA	500.00	400
			880.00	880.00
			Total	S\$ 1,746.70
			Add GST @ 7%	122.27
			Total Amount Payable	S\$ 1,868.97

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: