



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CS3/LPC20009042/Gtd3e2-1

300 BEACH ROAD
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 09-12-2020



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBE 4967J	Veh. Inspected	SLJ 1417E
Policy No.		Coverage (\$)	0.00
Claim No.	20/20/20/VC05/023580	Excess (\$)	0.00
Assign From	KENNY LIM	Assign Date	24/11/2020

2. Vehicle Particulars & Condition

Make & Model	HONDA SHUTTLE 1.5G	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	GK81007587	Colour	BLUE
Odometer	80502	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/60 R15	FIRESTONE	6 mm
L/H Front Tyre	195/60 R15	FIRESTONE	6 mm
R/H Rear Tyre	195/60 R15	FIRESTONE	6 mm
L/H Rear Tyre	195/60 R15	FIRESTONE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	24/08/2020	Inspection Date	27/08/2020
Survey held at	CHIP SOON AUTO SUPPLY CO. BLK 9002 #01-74 TAMPINES STREET 93 TAMPINES INDUSTRIAL PARK A SINGAPORE 528836		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------