



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CS/FCI20012977/Ktf3e2	
			Date: 23/12/2020	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 3949M	Veh. Inspected	SGZ 1121H	
Policy No.		Coverage (\$)	0.00	
Claim No.	D20004798MFSH	Excess (\$)	0.00	
Assign From	WOO JUN KIATERIC	Assign Date	24/11/2020	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA ESTIMA	c.c	2362	
Engine No.	HIDDEN	Year of Reg.	2007	
Chassis No.	ACR507053273	Colour	METALLIC BLUE	
Odometer	170856 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	KAPSEN	8 mm	
L/H Front Tyre	215/60 R16	KAPSEN	8 mm	
R/H Rear Tyre	215/60 R16	TOYO	8 mm	
L/H Rear Tyre	215/60 R16	TOYO	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	23/11/2020	Inspection Date	01/12/2020	
Survey held at	EM SOLUTION PTE LTD 160 SIN MING DRIVE #03-18/19 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	