

SINGAPORE CIVIL DEFENCE FORCE

FIRE REPORT

1. GENERAL INFORMATION				
LOCATION OF FIRE: In front Centralised Rubbish Chute				
		Block 227B, Compassvale Drive Singapore 541227		
2. INCIDENT INFORMATION				
FIRE INVOLVED: A Honda Vezel car (SLA6784J) at the above said location.				
METHOD OF EXTINGUISHMENT: By SCDF crew using compressed air foam backpack and a 38mm hose line jet from fire appliances.				

PROBABLE CAUSE OF FIRE: Accidental (Electrical origin near dashboard)

DAMAGE SUSTAINED: As a result of the fire, the car was damaged. Miscellaneous items close to the vehicle sustained varying degrees of heat and smoke damage.

3. FATALITY/INJURY INFORMATION

NAME	PIN/FIN		DEAD/INJURIES SUSTAINED
NIL	NIL	NIL	NIL

REPORT CERTIFIED TRUE AND CORRECT BY:

EE YONG EN JOEL for COMMISSIONER SINGAPORE CIVIL DEFENCE FORCE

This is a computer generated Fire Report. No signature is required.