

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Reg. No: 19960/198R GST Reg. No. 19-960/198-R						
Affiliated to Federation Internationale Des Experts En Automobile						
	AUTO & GENERA	L INSURANCE (S) PL	-	Ref:	CS/AGI20012983/T1tf3q2	
	(BUDGET DIRECT 190 CLEMENCEAI SINGAPORE SHO 239924	INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	I	Date:	26/02/2021	
			(Code:	AGI	
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	SKQ 8788M	Veh. Inspected		SLG 8307J	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	C10008061/JM	Excess (\$)		0.00	
	Assign From	ABIGAIL CHOO	Assign Date		25/11/2020	
2. Vehicle Particulars & Condition						
	Make & Model	HONDA HRV	c.c		1496	
	Engine No.	HIDDEN	Year of Reg.		2016	
	Chassis No.	JHMRU1810GX200301	Colour		RED	
	Odometer	46544 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	215/60 R16	DUNLOP		6 mm	
	L/H Front Tyre	215/60 R16	DUNLOP		6 mm	
	R/H Rear Tyre	215/60 R16	DUNLOP		6 mm	
	L/H Rear Tyre	215/60 R16	DUNLOP		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	21/11/2020	Inspection Date	!	25/11/2020	
	Survey held at	at TEAMWORK GARAGE PTE LTD				
		53 UBI AVENUE 1 #01-24 SINGAPORE 408934.				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	,	Estimate Days of Repair				

5 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: