



Pte Ltd

53 Ubi Avenue 1 #01-23/24 Spore 408934

Paya Ubi Industrial Park

Tel : 6844 2475

E-mail : claims@teamworkgarage.com

ROC number : 201015366H

REPAIR PERFORMA INVOICE

BUDGET DIRECT

Vehicle number	SLG8307J
Make / Model	HONDA HRV
Chassis number	JHMRU1810GX200301
Accident date	21/11/20
Reference	2011-34

Qty	Particulars	Unit Price - SGD \$	
<u>PARTS REPLACEMENT - LIST ITEMS</u>			
1	TAILGATE	1287.60 <i>bl</i>	877.90.
1	TAILGATE INNER TRIM BOARD	225.00 <i>Xun</i>	
2	TAILGATE LAMP	<i>RHx</i> 570.00 <i>44?ora</i>	285
1	TAILGATE LOCK	269.50 <i>?bt</i>	118.20.
1	TAILGATE LOCK STRIKER	91.00 <i>Ry</i>	
1	TAILGATE WEATHERSTRIP	227.00 <i>?twil</i>	189
1	TAILGATE EMBLEM - HRV	56.20 <i>re</i>	
1	TAILGATE EMBLEM - I-VTEC	65.00 <i>we</i>	
1	TAILGATE EMBLEM - LOGO	70.00 <i>re</i>	
2	TAILGATE HINGE	121.00 <i>Xun</i>	
2	TAILLAMP	1390.00 <i>Xun</i>	
1	WINDSCREEN MOULDING	141.80 <i>ak</i>	
1	REAR BUMPER	950.60 <i>gle</i>	508.70.
1	REAR BUMPER LOWER GARNISH	425.00 <i>Xun</i>	
2	REAR BUMPER REFLECTOR	303.80 <i>Xun</i>	
2	REAR BUMPER RETAINER	<i>Ryx</i> 101.80 <i>44-Xun</i>	
2	REAR CORNER BUMPER	450.60 <i>Ry</i>	
1	FLOOR SPONGE TRAY BOARD	197.80 <i>Xun</i>	
1	END PANEL	585.80 <i>Ry</i>	
1	END PANEL TOP GARNISH	160.50 <i>?de</i>	
		7690.00	2472.30
	Less 20%	1538.00	
		6152.00	1977.84
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>			
1 SET	REAR BUMPER CLIP	30.00 <i>ak</i>	
1	REAR WINDSCREEN SEALANT	150.00 <i>80we</i>	
1 SET	END PANEL TOP GARNISH CLIP	50.00 <i>200re</i>	
1 SET	REAR REVERSE SENSOR	400.00 <i>200re</i>	
1 SET	REAR REVERSE SENSOR BUZZER	150.00 <i>Xun</i>	330.
	Subtotal	780.00	
<u>LABOUR AND MISCELLANEOUS CHARGES</u>			
	Balance B/F	6932.00	
1	CHECK WIRING AND LIGHTNING SYSTEM	80.00 <i>30</i>	
2	REMOVE AND REFIT INNER GARNISHES & TRIMS	150.00 <i>60</i>	
3	REMOVE AND REFIT REAR REVERSE SENSOR	150.00 <i>30</i>	

4	REMOVE AND REFIT WINDSCREEN GLASS	180.00 120	
5	PANEL BEATING ON AFFECTED AREAS	1400.00 600	
6	SPRAY PAINTING ON AFFECTED AREAS	1200.00 600	
7	APPLY ANTI RUST ON AFFECTED AREAS	150.00 30	
Subtotal		3310.00	1470
Grand total		10242.00	

Taylor 97495749  
 'WP' 25/11/20 @ 11am  
 Lumpsum 5 day  
 Resurvey after repair  
 Taylor @ lkkauto.com

1477.84  
 330  
 1470  
 3777.84  
 4543000 #  
 5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: