



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

AUTO & GENERAL INSURANCE (S) PL
(BUDGET DIRECT INSURANCE)
190 CLEMENCEAU AVENUE #03-01
SINGAPORE SHOPPING CENTRE
SINGAPORE 239924

INV No. AC2008243
INV Date 10/12/2020
Reference CS/AGI20012989/Atf3q2
Code AGI



PROFESSIONAL SERVICE FEE

Vehicle No. SLA 5940G
Insured Veh. SMK 6537S
Claim No. C10008101/ST
Policy No.
Accident Date 24/11/2020
Inspection Date 25/11/2020

Description	Total
Survey Inspection	250.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	250.00
GST (7%)	17.50
Grand Total	267.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL

Ref : CS/AGI20012989/Atf3q2

(BUDGET DIRECT INSURANCE)

190 CLEMENCEAU AVENUE #03-01

SINGAPORE SHOPPING CENTRES SINGAPORE

239924

Date : 10-12-2020



Code : AGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMK 6537S	Veh. Inspected	SLA 5940G
Policy No.		Coverage (\$)	0.00
Claim No.	C10008101/ST	Excess (\$)	0.00
Assign From	ABIGAIL CHOO	Assign Date	25/11/2020

2. Vehicle Particulars & Condition

Make & Model	HONDA VEZEL	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	RU11111573	Colour	BLUE
Odometer	458726	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	HABILEAD	6 mm
L/H Front Tyre	215/60 R16	HABILEAD	6 mm
R/H Rear Tyre	215/60 R16	HABILEAD	6 mm
L/H Rear Tyre	215/60 R16	HABILEAD	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	24/11/2020	Inspection Date	25/11/2020
Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLA 5940G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT RH DOOR	TO REPAIR SEE LABOUR	1,080.50	-
1	FRONT RH DOOR BLACK TAPE	NOT NECESSARY	35.00	-
1	REAR AXLE	BENT	1,650.00	1,650.00
1	REAR BUMPER	CUT	463.00	463.00
1	REAR BUMPER SIDE COVER RH	TO REPAIR SEE LABOUR	195.00	-
2	REAR BUMPER SIDE RETAINER L/R @\$23.00	NOT NECESSARY	46.00	-
1	REAR RH DOOR	DENTED	930.60	930.60
1	REAR RH DOOR BLACK TAPE	NECESSARY	35.00	35.00
1	REAR RH DOOR CHECKER	NOT NECESSARY	57.50	-
1	REAR RH DOOR GLASS REGULATOR WITH MOTOR	DAMAGED	390.00	390.00
1	REAR RH DOOR HINGE (LOWER)	NOT NECESSARY	55.00	-
1	REAR RH DOOR HINGE (TOP)	NOT NECESSARY	55.00	-
1	REAR RH DOOR INNER RUBBER GUIDE STOPPER	NOT NECESSARY	15.00	-
1	REAR RH DOOR INNER TRIM BOARD	NOT NECESSARY	498.00	-
1	REAR RH DOOR MECHANISM LOCK	NOT NECESSARY	210.00	-
1	REAR RH DOOR TRANSPARENT STICKER	NECESSARY	35.00	35.00
1	REAR RH DOOR WEATHER STRIP	NOT NECESSARY	109.00	-
1	REAR RH DOOR WEATHER STRIP (LOWER)	NOT NECESSARY	89.00	-
1	REAR RH DOOR WEATHER STRIP (VERTICAL)	CUT	65.00	65.00
1	REAR RH FENDER ARCH GARNISH	CUT	153.90	153.90
1	REAR RH SHOCK ABSORBER	NECESSARY	385.00	385.00
1	REAR RH WHEEL BEARING	DAMAGED	263.50	263.50
1	ROCKER GARNISH RH	CUT	377.50	377.50
	LESS 20% DISCOUNT		-1,438.70	-949.70
			5,754.80	3,798.80
1	REAR RH SPORT RIM (SN)	CUT	813.00	450.00
	LESS 20% DISCOUNT		-162.60	-
			650.40	450.00

Report Ref No. CS/AGI20012989/Atf3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>SPECIAL NETT ITEMS</u>			
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	50.00	30.00
1	REAR RH 215/60R16 TYRE (SN)	NOT NECESSARY	380.00	-
1	REAR RH DOOR INNER SPEAKER (SN)	CRACKED	400.00	180.00
1	SET REAR RH DOOR INNER TRIM BOARD CLIPS (SN)	NOT NECESSARY	50.00	-
1	SET REAR RH FENDER ARCH GARNISH CLIPS (SN)	NECESSARY	40.00	20.00
1	SET ROCKER GARNISH RH CLIPS (SN)	NECESSARY	50.00	30.00
			970.00	260.00
	<u>LABOUR</u>			
	TO REMOVE,REINSTALL ELECTRICAL WIRING HARNESS,CHECK LIGHTING,AND REWIRE FOR PARKING SENSOR.		80.00	50.00
	TO REMOVE,CHANGE REAR SUSPENSION PARTS,AXLE CARRIAGE,ABSORBER,LOWER ARM,TOP ARM,TRAILING ARM,KNUCKLE ARM,WHEEL BEARING,BEARING HUB AND ETC.		400.00	300.00
	TO ROAD TEST DRIVING,CHECK AND RESETTNG WHEEL ALIGNMENTS SYSTEM.		100.00	80.00
	TO TRANSFER DOOR GLASS,REGULATOR GEAR,MOTOR,RAILING,CHANNEL,TRIM BOARD,MECHANISM LOCK AND HANDLE.		80.00	80.00
	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS,REPAIR PORTION,AND WHERE CONSISTENT TO THE ACCIDENT.		1,000.00	600.00
	TO PROVIDE LABOUR,WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS,REPAIR,RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT.INCLUSIVE OF THE REPAIR OF FRONT RH DOOR AND REAR BUMPER SIDE COVER RH.		700.00	400.00
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.		100.00	60.00
	-		-	-
	-		-	-
	-		-	-
			2,460.00	1,570.00
GRAND TOTAL			9,835.20	6,078.80

Report Ref No. CS/AGI20012989/Atf3q2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,800.00
---	--	--	-----------------

Report Ref No. CS/AGI20012989/Atf3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLA 5940G

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLA 5940G

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLA 5940G

RE-INSPECTION

