

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

TWINCAR LEASING PTE LTD
2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT
AUTOHUB
SINGAPORE 417921

Contact : 83802233 96867734

TP Budget Direct
Denise.

ESTIMATE

Repair Code : CLM16558

Date in : 24/11/2020

Vehicle Num. : SLA5940G

Model : HONDA VEZEL 1.5X CVT

Chassis/Eng# : RU11111573/L15B4031578

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT RH DOOR <i>Reps</i>	1	1080.50	X 1,080.50
FRONT RH DOOR BLACK TAPE <i>neu</i>	1	35.00	+ 35.00
REAR AXLE <i>Best</i>	1	1650.00	✓ 1,650.00
REAR BUMPER <i>cut</i>	1	463.00	✓ 463.00
REAR BUMPER SIDE COVER RH <i>Reps</i>	1	195.00	+ 195.00
REAR BUMPER SIDE RETAINER L/R <i>neu</i>	2	23.00	+ 46.00
REAR RH DOOR <i>Dented</i>	1	930.60	✓ 930.60
REAR RH DOOR BLACK TAPE <i>neu</i>	1	35.00	✓ 35.00
REAR RH DOOR CHECKER <i>neu</i>	1	57.50	+ 57.50
REAR RH DOOR GLASS REGULATOR WITH MOTOR <i>Dented</i>	1	390.00	✓ 390.00
REAR RH DOOR HINGE (LOWER) <i>neu</i>	1	55.00	+ 55.00
REAR RH DOOR HINGE (TOP)	1	55.00	+ 55.00
REAR RH DOOR INNER RUBBER GUIDE STOPPER <i>neu</i>	1	15.00	+ 15.00
REAR RH DOOR INNER TRIM BOARD <i>neu</i>	1	498.00	+ 498.00
REAR RH DOOR MECHANISM LOCK <i>neu</i>	1	210.00	+ 210.00
REAR RH DOOR TRANSPARENT STICKER <i>neu</i>	1	35.00	✓ 35.00
REAR RH DOOR WEATHER STRIP <i>neu</i>	1	109.00	+ 109.00
REAR RH DOOR WEATHER STRIP (LOWER) <i>neu</i>	1	89.00	+ 89.00

*** This is a computer-generated document which requires no signature.***



N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

TWINCAR LEASING PTE LTD
2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT
AUTOHUB
SINGAPORE 417921

Contact : 83802233 96867734

ESTIMATE

Repair Code : CLM16558

Date in : 24/11/2020

Vehicle Num. : SLA5940G

Model : HONDA VEZEL 1.5X CVT

Chassis/Eng# : RU11111573/L15B4031578

REAR RH DOOR WEATHER STRIP (VERTICAL) <i>ct</i>	1	65.00	✓	65.00
REAR RH FENDER ARCH GARNISH <i>ct</i>	1	153.90	✓	153.90
REAR RH SHOCK ABSORBER <i>new</i>	1	385.00	✓	385.00
REAR RH SPORT RIM <i>ct</i>	1	813.00	<i>450 (SN)</i>	813.00
REAR RH WHEEL BEARING <i>new</i>	1	263.50	✓	263.50
ROCKER GARNISH RH <i>ct</i>	1	377.50	✓	377.50
Subtotal before discount				8,006.50
Percentage discount 20%				1,601.30
Sub-total 1				6,405.20
REAR BUMPER CLIPS - SET <i>new</i>	1	50.00	<i>30</i>	50.00
REAR RH 215/60R16 TYRE <i>new</i>	1	380.00	X	380.00
REAR RH DOOR INNER SPEAKER <i>cracked</i>	1	400.00	<i>180</i>	400.00
REAR RH DOOR INNER TRIM BOARD CLIPS - SET <i>new</i>	1	50.00	X	50.00
REAR RH FENDER ARCH GARNISH CLIPS - SET <i>new</i>	1	40.00	<i>20</i>	40.00
ROCKER GARNISH RH CLIPS - SET <i>new</i>	1	50.00	<i>30</i>	50.00
Subtotal before discount				970.00
Percentage discount 0%				0.00
Sub-total 2				970.00
Parts-total				7,375.20

*** This is a computer-generated document which requires no signature.***



N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

TWINCAR LEASING PTE LTD

2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT

AUTOHUB

SINGAPORE 417921

Contact : 83802233 96867734

ESTIMATE

Repair Code : CLM16558

Date in : 24/11/2020

Vehicle Num. : SLA5940G

Model : HONDA VEZEL 1.5X CVT

Chassis/Eng# : RU11111573/L15B4031578

LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.

To remove, change rear suspension parts, axle carriage, absorber, lower arm, top arm, trailing arm, knuckle arm, wheel bearing, bearing hub and etc.

To road test driving, check and resetting wheel alignments system.

To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

Labour Total

Parts & Labour Total

2,460.00

9,835.20

*** This is a computer-generated document which requires no signature.***

page 3

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 6078.80

L/S : 48K ✓

50 80.00
300 400.00
80 100.00
80 80.00
1570 600 1,000.00
400 700.00
60 100.00

Adrian L
25/11/20
4/5 0.5 days