

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314

Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

24/11/2020

CHINA TAIPING INSURANCE (S) PTE LTD
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909.

Attention :- XA017

Page # :- 1

Veh # :- SKZ4733A

Veh Model :- HONDA JAZZ 1.3L AT

Estimate# :- CK421243

Claim # :-

ACC. Date :- 23/11/20

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	FRONT SPORT RIM LH <i>see</i>	1	PC 682.40	682.40
2.	FRONT KNUCKLE ARM LH <i>?bt</i>	1	PC 254.50	254.50
3.	FRONT KNUCKLE HUB LH <i>?bt</i>	1	PC 163.90	163.90
4.	FRONT KNUCKLE BEARING LH <i>?bt</i>	1	PC 123.30	123.30
5.	FRONT LOWER ARM LH <i>?bt</i>	1	PC 234.80	234.80
6.	FRONT SHOCK ABSORBER LH <i>?bt</i>	1	PC 321.80	321.80
7.	FRONT DOOR RH <i>bt</i>	1	PC 859.90	859.90
8.	FRONT DOOR STICKER RH <i>ne</i>	1	PC 18.50	18.50
9.	FRONT DOOR OUTER HANDLE RH <i>repair ok</i>	1	PC 84.80	84.80
10.	FRONT DOOR LOCK RH <i>?jam</i>	1	PC 239.60	239.60
11.	FRONT DOOR WEATHERSTRIP RH <i>ne</i>	1	PC 96.40	96.40
12.	FRONT DOOR GLASS REGULATOR MOTOR RH - CHECK <i>?ok / 405.30</i>	1	PC	
13.	CENTER PILLAR RH <i>bt</i>	1	PC 602.90	602.90
14.	ROOF SIDE PANEL RH (REPAIR)	1	PC	
15.	REAR DOOR RH <i>bt</i>	1	PC 724.50	724.50
16.	REAR DOOR STICKER RH <i>ne</i>	1	PC 18.50	18.50
17.	REAR DOOR HINGE TOP RH <i>?bt</i>	1	PC 36.40	36.40
18.	REAR DOOR HINGE BOTTOM RH <i>bt</i>	1	PC 38.40	38.40
19.	REAR DOOR CHECKER RH <i>?bt</i>	1	PC 39.60	39.60
20.	REAR DOOR WEATHERTRIP RH <i>ne</i>	1	PC 103.90	103.90
21.	REAR DOOR LOCK RH <i>?bt</i>	1	PC 215.00	215.00
22.	REAR DOOR GLASS REGULATOR MOTOR RH - CHECK <i>?bt / 373.90</i>	1	PC	
23.	ROCKER PANEL RH <i>repair bt</i>	1	PC 401.30	401.30
24.	REAR FENDER RH <i>bt</i>	1	PC 675.90	675.90
25.	REAR BUMPER <i>de</i>	1	PC 520.40	520.40
26.	REAR SPORT RIM LH <i>end</i>	1	PC 682.40	682.40
27.	REAR SHOCK ABSORBER LH <i>?x cvc</i>	1	PC 189.80	189.80
28.	REAR WHEEL BEARING LH <i>?bt</i>	1	PC 240.60	240.60
29.	REAR AXLE <i>?bt</i>	1	PC 1,221.30	1,221.30
LIST TOTAL S\$				8,790.80
20% DISCOUNT S\$				-1,758.16
				7,032.64

SPECIAL NET ITEMS :

1.	FRONT TYRE LH <i>?cut</i>	1	PC 160.00	70% 160.00
2.	REAR QUARTER GLASS SEALANT RH <i>ne</i>	1	PC 40.00	40.00
3.	REAR TYRE LH <i>?cut</i>	1	PC 160.00	70% 160.00

SPECIAL NET TOTAL S\$

360.00

LABOUR :

TO CUT/WELD REAR FENDER RH, CENTER PILLAR RH, ROCKER PANEL RH. KNOCK AND STRAIGHTEN ROOF PANEL RH, FRONT DOOR LH, REAR DOOR LH. REMOVE AND REPLACE ACCIDENT DAMAGED PARTS. REALIGN ALL CONNECTION

1400
1200 1,680.00

Estimate

24/11/2020

CHINA TAIPING INSURANCE (S) PTE LTD
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909.

Attention :- XA017

Page # :- 1 139553
Veh # :- SKZ4733A
Veh Model :- HONDA JAZZ 1.3L AT
Estimate# :- CK421243
Claim # :-
ACC. Date :- 23/11/20
Terms :- C.O.D Days
Remarks :-

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg
Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

No.	Description	Qty	U.Price	Amounts S\$
	SPRAY PAINT FRONT DOORS RH & LH, CENTER PILLAR RH, ROCKER PANEL RH, ROOF PANEL, REAR DOORS RH & LH, REAR FENDER RH, REAR BUMPER	1300	1500.00	1950.00
	REMOVE & REINSTALL FRONT UNDERCARRIAGE SUSPENSION LH	100	150.00	150.00
	REMOVE & REFIT FRONT DOOR MECHANISM AND CHECK LOCKING SYSTEM	14 days + 2 = 16 days	50.00	800.00
	REMOVE & REFIT REAR DOOR TRIM BOARD, MECHANISM AND CHECK LOCKING SYSTEM	45	50.00	2250.00
	REMOVE & REFIT FRONT AND REAR SEAT ASSY, FLOOR CARPET, SIDE GARNISH, INNER TRIM	25/11/2020 @ 1520	80	150.00
	REMOVE & REFIT REAR QUARTER GLASS RH	60	80.00	4800.00
	REMOVE & REINSTALL REAR SUSPENSION, REAR AXLE	Resy after repair	150	200.00
	COMPUTER WHEEL ALIGNMENT		60.00	60.00
	RUST PROOF AFFECTED AREAS	100	150.00	15000.00
	LABOUR TOTAL S\$			4,040.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

E. & O.E

Acknowledged by Repairer

Signature:

Customer's Signature/Co. Stamp MOVA AUTOMOTIVE PTE LTD

NON-TAX AMOUNT S 12,994.96
AMOUNT S\$ 11,452.04
GST @ 7 % 800.28
AMOUNT DUE S\$ 12,232.92

Main Office:
 Mova Building
 No. 22, Jalan Kilang,
 Singapore 159419
 Tel : (65) 6476 3333
 Fax : (65) 6271 5891
 www.mova.com.sg

Workshop Dept:
 Block 1008,
 Bukit Merah Lane 3,
 #01-04/06/08/94
 Singapore 159722

Tel : (65) 6272 3892
 Fax : (65) 6270 8314
 Co. Reg. 198904033G
 GST Reg. M2-0088864-2

SUPPLEMENTARY

CHINA TAIPING INSURANCE (S) PTE LTD
 3 ANSON ROAD
 #16-00 SPRINGLEAF TOWER
 SINGAPORE 079909

Page : 1
 Veh No : SKZ4733A
 Model : HONDA JAZZ 1.3L AT
 Acc Date : 23-Nov-20
 Incharge : BILLY

No	Description	Qty	U.Price	Amt \$
LIST ITEMS :				
1	REAR BRAKE CALIPER LH bt	1	\$ 394.50	\$394.50
2	FRONT DOOR GLASS REGULATOR MOTOR RH cut	1	\$ 405.30	\$405.30
3	REAR DOOR GLASS REGULATOR MOTOR RH bt	1	\$ 373.90	\$373.90

LIST TOTAL S\$	\$1,173.70
20% DISCOUNT S\$	\$234.74
	<u>\$938.96</u>

1) PARTS 7819.76
 2) SMT 264.00
 3) LABOUR 3350.00
 11433.76
 - 2286.75 10% 20%
 9147.01

Lump sum @ 9100.00 16 DAYS.

PLEASE ADVISE. THANK YOU
 BILLY LIAN.

NON-TAX AMOUNTS	\$938.96
GST @ 7%	\$65.73
AMOUNT DUE	<u>\$1,004.69</u>



Customer's Signature/Co.Stamp

MOVA AUTOMOTIVE PTE LTD