

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No: 199607198R GST Reg. No. 19-9607198-R				
Affiliated to Federation Internationale Des Experts En Automobile					
AUT	O & GENERAL IN	SURANCE (S) PL	Ref : CS/AGI20013005/F	ef : CS/AGI20013005/R1qf3e2	
(BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Date: 07-12-2020		
			Code: AGI		
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SJK 9030C	Veh. Inspected	SKP 3636G	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	C10008079/JM	Excess (\$)	0.00	
	Assign From	ABIGAIL CHOO	Assign Date	25/11/2020	
2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA VIOS E AUTO	c.c	1497	
	Engine No.	HIDDEN	Year of Reg.	2008	
	Chassis No.	MR053HY9305044112	Colour	BLACK	
	Odometer	160663	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	FAIR			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	185/60 R15	FIRENZA	5 mm	
	L/H Front Tyre	185/60 R15	FIRENZA	5 mm	
	R/H Rear Tyre	185/60 R15	FIRENZA	5 mm	
	L/H Rear Tyre	185/60 R15	FIRENZA	5 mm	
4.					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	23/11/2020	Inspection Date	26/11/2020	
	Survey held at ACCORD AUTO SERVICES PTE LTD				
		BLK 1009 BUKIT MERAH LANE 3 #01-80 SINGAPORE 159723			
5a.	ia. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.		Estimate Days of Repair			

4 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: