

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
	BLUWEL AUTOMO	OTIVE SERVICE PTE LTD	Ref:	CS/TP20013007/Ucf3e2
	BLK 1 KAKI BUKIT #01-28/51/53/55(M 417883	AVE 6 AIN OFFICE)SINGAPORE	Date:	19/01/2021
	ON BEHALF OF Y	EO SIEW HONG	Code:	TP149
1.	Policy Particulars :- THIRD PARTY CLAIM			
	Insured Veh.		Veh. Inspected	SDP 9003B
	Policy No.		Coverage (\$)	0.00
	Claim No.		Excess (\$)	0.00
	Assign From		Assign Date	25/11/2020
2. Vehicle Particulars & Condition				
	Make & Model	MERCEDES BENZ GLC250 COUPE AMG (A)	c.c	1991
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	WDC2533462F408550	Colour	WHITE
	Odometer	31647 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
		0.20		
	R/H Front Tyre	235/55 R19	PIRELLI	8 mm
	R/H Front Tyre L/H Front Tyre		PIRELLI PIRELLI	8 mm 8 mm
		235/55 R19		-
	L/H Front Tyre	235/55 R19 235/55 R19	PIRELLI	8 mm
4.	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre	235/55 R19 235/55 R19 255/50 R19 255/50 R19 Description	PIRELLI HANKOOK HANKOOK on of Damages	8 mm 6 mm 6 mm
4.	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre	235/55 R19 235/55 R19 255/50 R19 255/50 R19	PIRELLI HANKOOK HANKOOK on of Damages	8 mm 6 mm 6 mm
4.	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre THE VEHICLE SUS	235/55 R19 235/55 R19 255/50 R19 255/50 R19 Description	PIRELLI HANKOOK HANKOOK on of Damages	8 mm 6 mm 6 mm
4.	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre THE VEHICLE SUSTO COLLISION.	235/55 R19 235/55 R19 255/50 R19 255/50 R19 Description STAINED DAMAGES AT THE FROM ETAILS.	PIRELLI HANKOOK HANKOOK on of Damages	8 mm 6 mm 6 mm
	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre THE VEHICLE SUSTO COLLISION.	235/55 R19 235/55 R19 255/50 R19 255/50 R19 Description STAINED DAMAGES AT THE FROM ETAILS.	PIRELLI HANKOOK HANKOOK On of Damages ONT PORTION. THE CHAS	8 mm 6 mm 6 mm
	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre THE VEHICLE SUSTO COLLISION. DAMAGES SEE D	235/55 R19 235/55 R19 255/50 R19 255/50 R19 Description STAINED DAMAGES AT THE FROM ETAILS. General	PIRELLI HANKOOK HANKOOK ON of Damages ONT PORTION. THE CHAS	8 mm 6 mm 6 mm SSIS FRAME AFFECTED DUE
	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre THE VEHICLE SUSTO COLLISION. DAMAGES SEE D	235/55 R19 235/55 R19 255/50 R19 255/50 R19 Description STAINED DAMAGES AT THE FROM ETAILS. General 21/11/2020	PIRELLI HANKOOK HANKOOK ON OF Damages ONT PORTION. THE CHAS	8 mm 6 mm 6 mm SSIS FRAME AFFECTED DUE
	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre THE VEHICLE SUSTO COLLISION. DAMAGES SEE D	235/55 R19 235/55 R19 255/50 R19 255/50 R19 Description STAINED DAMAGES AT THE FROM ETAILS. General 21/11/2020 BLUWEL AUTOMOTIVE SERVIOR BLK 1 KAKI BUKIT AVE 6 #01-28/51/53/55(MAIN OFFICE) SINGAPORE 417883	PIRELLI HANKOOK HANKOOK ON OF Damages ONT PORTION. THE CHAS	8 mm 6 mm 6 mm SSIS FRAME AFFECTED DUE
5.	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre THE VEHICLE SUSTO COLLISION. DAMAGES SEE D Accident Date Survey held at	235/55 R19 235/55 R19 255/50 R19 255/50 R19 Description STAINED DAMAGES AT THE FROM ETAILS. General 21/11/2020 BLUWEL AUTOMOTIVE SERVIOR BLK 1 KAKI BUKIT AVE 6 #01-28/51/53/55(MAIN OFFICE) SINGAPORE 417883	PIRELLI HANKOOK HANKOOK ON OF Damages ONT PORTION. THE CHAST I Information Inspection Date CE PTE LTD Emarks THOUT PREJUDICE" BASIS	8 mm 6 mm 6 mm SSIS FRAME AFFECTED DUE 25/11/2020
5.	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre THE VEHICLE SUSTO COLLISION. DAMAGES SEE D Accident Date Survey held at	235/55 R19 235/55 R19 255/50 R19 255/50 R19 Description STAINED DAMAGES AT THE FROM ETAILS. General 21/11/2020 BLUWEL AUTOMOTIVE SERVIOR BLK 1 KAKI BUKIT AVE 6 #01-28/51/53/55(MAIN OFFICE) SINGAPORE 417883 RON WAS CONDUCTED ON A"WITCE TO YOUR INSTRUCTIONS, W	PIRELLI HANKOOK HANKOOK ON OF Damages ONT PORTION. THE CHAST I Information Inspection Date CE PTE LTD Emarks THOUT PREJUDICE" BASIS	8 mm 6 mm 6 mm SSIS FRAME AFFECTED DUE 25/11/2020
5. 5a.	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre THE VEHICLE SUSTO COLLISION. DAMAGES SEE D Accident Date Survey held at A)THE INSPECTIC B)IN ACCORDANCE	235/55 R19 235/55 R19 255/50 R19 255/50 R19 Description STAINED DAMAGES AT THE FROM ETAILS. General 21/11/2020 BLUWEL AUTOMOTIVE SERVIOR BLK 1 KAKI BUKIT AVE 6 #01-28/51/53/55(MAIN OFFICE) SINGAPORE 417883 RON WAS CONDUCTED ON A"WITCE TO YOUR INSTRUCTIONS, W	PIRELLI HANKOOK HANKOOK ON OF Damages ONT PORTION. THE CHAST I Information Inspection Date CE PTE LTD Emarks THOUT PREJUDICE" BASIS TE HAVE NOT AUTHORISE Days of Repair	8 mm 6 mm 6 mm SSIS FRAME AFFECTED DUE 25/11/2020