

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SMS5150M**LAD2011-002***Not Authorised
Resurvey BP paint*

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :
Date of Registration:

23 NOV 2020**SMS5150M**

JTDKB3FU703091068

TOYOTA

PRIUS

20/11/2020

AIA

28/02/2020

		LIST	
		PART	
1	COVER, REAR BUMPER	\$	BT/cm 485.60 ✓
1	ABSORBER ASSY, SHOCK, REAR LH	\$	NSP 127.00 X
1	REINFORCEMENT SUB-ASSY, REAR BUMPER	\$	Bz 332.70 ✓
1	GUARD, REAR BUMPER, CENTER	\$	CM 374.50 ✓
1	REFLECTOR ASSY, REFLEX, LH	\$	CM 39.00 ✓
1	COVER, REAR BUMPER, LOWER	\$	SL 22.00 X
1	RETAINER, REAR BUMPER SIDE, LH	\$	DIY 132.60 ✓
1	RETAINER, REAR BUMPER SIDE, RH	\$	SL 132.60 X
1	PANEL SUB-ASSY, BACK DOOR	\$	Bz 1,147.80 ✓
1	HINGE ASSY, BACK DOOR, LH	\$	R 61.00 X
1	HINGE ASSY, BACK DOOR, RH	\$	R 61.00 X
1	STAY ASSY, BACK DOOR, LH	\$	SL 242.50 X
1	STAY ASSY, BACK DOOR, RH	\$	SL 242.50 A
1	GLASS, BACK WINDOW FIX	\$	Shatterw 761.40 ✓
1	GARNISH SUB-ASSY, BACK DOOR, OUTSIDE	\$	CM 913.60 ✓
1	ORNAMENT SUB-ASSY, BACK DOOR	\$	NS 47.90 ✓
1	PLATE, LUGGAGE COMPARTMENT DOOR NAME, NO.2	\$	NS 54.60 ✓
1	PLATE, BACK DOOR NAME, NO.1	\$	NS 54.60 ✓
1	LENS & BODY, REAR COMBINATION LAMP, NO.2 RH	\$	SL 261.00 X
1	LENS & BODY, REAR COMBINATION LAMP, RH	\$	SL 339.60 X
1	LENS & BODY, REAR COMBINATION LAMP, NO.2 LH	\$	CM 261.00 ✓
1	LENS & BODY, REAR COMBINATION LAMP, LH	\$	CM 339.60 ✓
1	PANEL SUB-ASSY, QUARTER, LH	\$	R 871.50 X
1	PANEL SUB-ASSY, QUARTER, RH	\$	R 871.50 X
1	DUCT ASSY, QUARTER VENT, LH	\$	SL 67.00 X
1	LINER, REAR WHEEL HOUSE, LH	\$	SL 139.80 X

Trans-cab Auto Services Pte Ltd**LAD2011-002**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SMS5150M

- 1 LINER, REAR WHEEL HOUSE, RH
- 1 PANEL SUB-ASSY, BODY LOWER BACK
- 1 COVER, FLOOR UNDER, NO.1 (LH)
- 1 COVER, FLOOR UNDER, NO.2 (RH)
- 1 COVER, REAR FLOOR (CTR)
- 1 PAN, REAR FLOOR
- 1 BOX, DECK FLOOR, LH

\$	<i>Ph</i>	139.80	X
\$	<i>Ph</i>	651.00	✓
\$	<i>Ph</i>	175.10	✓
\$	<i>Ph</i>	241.90	X
\$	<i>Ph</i>	229.90	X
\$	<i>Ph</i>	583.40	X
\$	<i>Ph</i>	313.00	X
TOTAL	\$	6,434.10	
25%	\$	1,608.53	
	\$	4,825.58	

Special Nett

- 1SET PARKING AID
- 1SET REAR BUMPER CLIP
 - 1 WHEELHOUSE LINER CLIP
 - 1 BUMPER CENTRE GUARD CLIP
 - 1 REAR TAILGATE STICKER 'TRANS-CAB'
 - 1 REAR TAILGATE STICKER '6555-3333'
 - 1 REAR BUMPER PROTECTOR
 - 1 REAR BUMPER RETAINER CLIP
- 1SET TAILLAMP CLIP
- 2 WINDSCREEN SEALANT
- 1 WINDSCREEN MOULDING
- 1 WINDSCREEN INNER SPONGE SEAL

\$	<i>Shan</i>	700.00	<i>2205m</i>
\$	<i>Ph</i>	85.00	<i>551m</i>
\$	<i>nn</i>	70.00	} X
\$	<i>nn</i>	80.00	
\$	<i>nn</i>	80.00	
\$	<i>nn</i>	80.00	
\$	<i>nn</i>	80.00	
\$	<i>nn</i>	180.00	} X
\$	<i>nn</i>	75.00	
\$	<i>nn</i>	50.00	
\$	<i>nn</i>	150.00	<i>805m</i>
\$	<i>nn</i>	200.00	✓
\$	<i>nn</i>	130.00	<i>305m</i>
TOTAL	\$	1,400.00	

TOTAL PARTS \$ 6,225.58**LABOUR**

To Rust-Proofing and apply undercoat Of The Affected Areas.

\$ 240.00 *301*

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ 380.00 *601*

LAD2011-002

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SMS5150M

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 1,600.00 600

To transfer of rear end panel fittings, attachment to facilitate bodywork repair.

\$ 380.00 X

Putty And Spray Painting Of The Affected Portion.

\$ 1,600.00 880

To Remove And Refit Rear Big & Small W/Screen Glass To Facilitate Bodywork Repair.

\$ 300.00 180

To reinstall rear bumper parking sensor.

\$ 170.00 50

To Check Electrical Lighting Concerned.

\$ 170.00 20

TOTAL \$ 4,840.00

Over All Total \$ 11,065.58

(PART-BY-PART) Repair Days

10 Days

5 days

For Official Use

Prepared By : _____
(Accident Dept)

Verify By : _____

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: