



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2101926

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV Date 24/03/2021
Reference CC6/FCI20013013/Ura3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SJY 5169P
Insured Veh. SH 9737G
Claim No. D20004814MFSH
Policy No. D-18088937MFSH
Accident Date 23/11/2020
Inspection Date 25/11/2020

Description	Total
Third Party Express Settlement	600.00
Subtotal	600.00
GST (7%)	42.00
Grand Total	642.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC6/FCI20013013/Ura3q2	
			Date: 24/03/2021	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SH 9737G	Veh. Inspected	SJY 5169P
	Policy No.	D-18088937MFSH	Coverage (\$)	0.00
	Claim No.	D20004814MFSH	Excess (\$)	0.00
	Assign From	CHRIS LIM	Assign Date	25/11/2020
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA PRIUS (A)	c.c	1797
	Engine No.	HIDDEN	Year of Reg.	2010
	Chassis No.	ZVW305123371	Colour	BLUE
	Odometer	377169 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/55 R16	CONTINENTAL	6 mm
	L/H Front Tyre	205/55 R16	CONTINENTAL	6 mm
	R/H Rear Tyre	205/55 R16	CONTINENTAL	6 mm
	L/H Rear Tyre	205/55 R16	CONTINENTAL	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	23/11/2020	Inspection Date	25/11/2020
	Survey held at	FALCON-AIR AUTO SERVICES PTE LTD BLK 9006 TAMPINES ST 93 #01-200 SINGAPORE 528840		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJY 5169P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	DISTORTED	1,980.00	1,250.00
2	FRONT BUMPER SIDE RETAINER @\$95.00	NOT NECESSARY	190.00	-
1	FRONT BUMPER LOGO	SCRATCHED	95.00	95.00
1	FRONT BUMPER LOWER GRILLE	DEFORMED / TORN	225.00	170.00
1	FRONT BUMPER REINFORCEMENT	BENT	680.00	520.00
1	FRONT BUMPER SPONGE	TORN	80.00	80.00
1	RADIATOR GRILLE	CRACKED	350.00	300.00
1	FRONT BUMPER TOP RUBBER	NECESSARY	40.00	40.00
1	FRONT NUMBER PLATE BASE	DISTORTED	112.80	95.00
1	BONNET	DENTED	1,550.00	945.10
2	BONNET HINGES @\$137.00	BENT	274.00	274.00
1	BONNET LOCK-TOP	TWISTED	295.00	95.00
1	BONNET LOCK-BOTTOM	TWISTED	311.72	115.00
2	BONNET INSULATOR @\$395.00	NOT NECESSARY	790.00	-
2	FRONT BUMPER TOW COVER @\$38.10	NOT NECESSARY	76.20	-
2	FRONT FENDER @\$930.00	TO REPAIR SEE LABOUR	1,860.00	-
2	FRONT FENDER EMBLEM-HYBRID @\$85.00	NOT NECESSARY	170.00	-
2	HEADLAMP @\$1245.00	CRACKED	2,490.00	1,960.20
1	RADIATOR SUPPORT PANEL	BENT	1,764.70	1,464.70
1	RADIATOR SUPPORT TOP GARNISH	DISTORTED	267.80	245.10
1	AIR-CON CONDENSER	BENT	1,690.00	1,290.00
1	AIR-CON CONDENSER FAN MOTOR	NOT NECESSARY	478.90	-
1	RADIATOR	BENT / PUNCTURE	1,914.80	1,814.80
1	RADIATOR FAN COWLING	NOT NECESSARY	379.30	-
1	RADIATOR FAN MOTOR	NOT NECESSARY	588.30	-
1	RADIATOR FAN BLADE	NOT NECESSARY	279.00	-
1	WIPER WASHER TANK	NOT NECESSARY	183.60	-
2	HORN @\$155.00	NOT NECESSARY	310.00	-
1	FRONT BUMPER TOP SUPPORT	NOT NECESSARY	266.30	-
2	FRONT BUMPER REINFORCEMENT BRACKET @\$225.60	NOT NECESSARY	451.20	-

Report Ref No. CC6/FCI20013013/Ura3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BONNET TOP LOCK CATCH	REPEATED	78.30	-
1	AIR-CON CONDENSOR FAN BLADE	NOT NECESSARY	199.80	-
1	INTERCOOLER	BENT / PUNCTURE	1,074.00	1,050.00
1	FRONT BUMPER LOWER TRAY	TORN	247.20	247.20
	LESS 25% DISCOUNT		-5,435.73	-3,012.78
			16,307.19	9,038.32
	<u>SPECIAL NETT ITEMS</u>			
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	50.00	50.00
1	FRONT NUMBER PLATE (SN)	BENT	45.00	40.00
1	SET BONNET STICKER (SN)	NOT NECESSARY	180.00	-
1	SET BONNET INSULATOR CLIP (SN)	NOT NECESSARY	50.00	-
1	SET FRONT FENDER INNER SHIELD CLIP (SN)	NOT NECESSARY	80.00	-
1	SET RADIATOR SUPPORT TOP GARNISH CLIP (SN)	NECESSARY	50.00	30.00
2	RADIATOR SUPPORT TOP GARNISH STICKER @\$40.00 (SN)	NOT NECESSARY	80.00	-
2	HORN BRACKET @\$40.00 (SN)	NOT NECESSARY	80.00	-
1	BTL COOLANT (SN)	NECESSARY	30.00	30.00
			645.00	150.00
	<u>LABOUR</u>			
	TO CHECK LIGHT SYSTEM AND WIRING.		50.00	30.00
	ANTI-RUST.		120.00	60.00
	TO APPLY BODY SEALANT ON BODY JOINTS.	NOT NECESSARY	120.00	-
	TO VACCUM,REOIL AND REGAS AIR CON.		120.00	100.00
	TO RNR HYBRID SYSTEM.	NOT NECESSARY	400.00	-
	TO PLUG IN DIAGNOSTIC AND REPROGRAM HYBRID SYSTEM.		250.00	100.00
	LABOUR/PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRONT FENDER.		900.00	800.00
	TO PUTTY AND RESPRAY ACCIDENT DAMAGED PARTS.		1,200.00	1,000.00
			3,160.00	2,090.00
	GRAND TOTAL		20,112.19	11,278.32

Report Ref No. CC6/FCI20013013/Ura3q2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			9,000.00
---	--	--	----------

Report Ref No. CC6/FCI20013013/Ura3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJY 5169P

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJY 5169P

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJY 5169P

RE-INSPECTION






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

