



FALCON-AIR

MS FIRST CAPITAL INSURANCE LIMITED  
36 ROBINSON ROAD  
#16-01 CITY HOUSE SINGAPORE 068877

Attention : Motor Claim Department

Contact : 62222311 Fax No. : 62223547

Estimate : ES707788

Date : 24/11/2020  
Vehicle Num. : SJY 5169P  
Make/Model : TOYOTA PRIUS  
Chassis/Eng# : ZVW305123371  
Accident Date : 23/11/2020  
Claim No. :  
Reference :  
Policy No. :

LKK Jaslin  
Not Authorised  
2/5 #9000/  
25/11/20  
whaphc. After repair  
6 days.

| S/N | Quantity | Particular | Unit Price | Amount S\$ |
|-----|----------|------------|------------|------------|
|-----|----------|------------|------------|------------|

|              |      |                              |                          |          |
|--------------|------|------------------------------|--------------------------|----------|
| LIST ITEMS : |      |                              |                          |          |
| 1.           | 1PC  | FRONT BUMPER                 | DIS 1250                 | 1,980.00 |
| 2.           | 2PCS | FRONT BUMPER SIDE RETAINER   | 1 1                      | 190.00   |
| 3.           | 1PC  | FRONT BUMPER LOGO            | scr                      | 95.00    |
| 4.           | 1PC  | FRONT BUMPER LOWER GRILLE    | Re/torn 170              | 225.00   |
| 5.           | 1PC  | FRONT BUMPER REINFORCEMENT   | Bent 520                 | 680.00   |
| 6.           | 1PC  | FRONT BUMPER SPONGE          | Torn 300                 | 80.00    |
| 7.           | 1PC  | RADIATOR GRILLE              | one 300                  | 350.00   |
| 8.           | 1PC  | FRONT BUMPER TOP RUBBER      | rel                      | 40.00    |
| 9.           | 1PC  | FRONT NUMBER PLATE BASE      | DIS 95.00                | 112.80   |
| 10.          | 1PC  | BONNET                       | DD 945.10                | 1,550.00 |
| 11.          | 2PCS | BONNET HINGES                | Bent 137.00              | 274.00   |
| 12.          | 1PC  | BONNET LOCK - TOP            | twi 95.00                | 295.00   |
| 13.          | 1PC  | BONNET LOCK - BOTTOM         | twi 115.00               | 311.72   |
| 14.          | 2PCS | BONNET INSULATOR             | 1 1                      | 790.00   |
| 15.          | 2PCS | FRONT BUMPER TOW COVER       | 1 1                      | 76.20    |
| 16.          | 2PCS | FRONT FENDER                 | 2                        | 1,860.00 |
| 17.          | 2PCS | FRONT FENDER EMBLEM - HYBRID | 1 1                      | 170.00   |
| 18.          | 2PCS | HEADLAMP                     | cha 980.10 x 2 = 1960.20 | 2,490.00 |
| 19.          | 1PC  | RADIATOR SUPPORT PANEL       | Bent 1464.70             | 1,764.70 |
| 20.          | 1PC  | RADIATOR SUPPORT TOP GARNISH | DIS 245.10               | 267.80   |
| 21.          | 1PC  | AIR-CON CONDENSER            | Bent 1290.00             | 1,690.00 |
| 22.          | 1PC  | AIR-CON CONDENSER FAN MOTOR  | 1 1                      | 478.90   |

CONTINUE / ...

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1939.1


FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk 1 / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg



## FALCON-AIR

MS FIRST CAPITAL INSURANCE LIMITED  
36 ROBINSON ROAD  
#16-01 CITY HOUSE SINGAPORE 068877

Attention : Motor Claim Department

Contact : 62222311 Fax No. : 62223547

Estimate : ES707788

Date : 24/11/2020

Vehicle Num. : SJY 5169P

Make/Model : TOYOTA PRIUS

Chassis/Eng# : ZVW305123371

Accident Date : 23/11/2020

Claim No. :

Reference :

Policy No. :

| S/N                   | Quantity | Particular                                        | Unit Price | Amount S\$ |
|-----------------------|----------|---------------------------------------------------|------------|------------|
| 23.                   | 1PC      | RADIATOR <i>Bent/pun 1814.80</i>                  |            | 1,914.80   |
| 24.                   | 1PC      | RADIATOR FAN COWLING <i>11</i>                    |            | 379.30     |
| 25.                   | 1PC      | RADIATOR FAN MOTOR <i>11</i>                      |            | 588.30     |
| 26.                   | 1PC      | RADIATOR FAN BLADE <i>11</i>                      |            | 279.00     |
| 27.                   | 1PC      | WIPER WASHER TANK <i>11</i>                       |            | 183.60     |
| 28.                   | 2PCS     | HORN <i>11</i>                                    | 155.00     | 310.00     |
| 29.                   | 1PC      | FRONT BUMPER TOP SUPPORT <i>11</i>                |            | 266.30     |
| 30.                   | 2PCS     | FRONT BUMPER REINFORCEMENT BRACKET <i>11</i>      | 225.60     | 451.20     |
| 31.                   | 1PC      | BONNET TOP LOCK CATCH <i>Repet 11</i>             |            | 78.30      |
| 32.                   | 1PC      | AIR-CON CONDENSOR FAN BLADE <i>11</i>             |            | 199.80     |
| 33.                   | 1PC      | INTERCOOLER <i>Bent/pun 1050</i>                  |            | 1,074.00   |
| 34.                   | 1PC      | Front bumper lower tray <i>Torn</i>               |            | 247.20     |
| List TotalS\$ :       |          |                                                   |            | 21,742.92  |
| 25.00% Discount S\$ : |          |                                                   |            | 5,435.73   |
|                       |          |                                                   |            | 16,307.19  |
| 1.                    | 1SET     | SPECIAL NETT ITEMS : FRONT BUMPER CLIP <i>new</i> |            | 50.00      |
| 2.                    | 1PC      | FRONT NUMBER PLATE <i>Bent</i>                    |            | 45.00      |
| 3.                    | 1SET     | BONNET STICKER <i>11</i>                          |            | 180.00     |
| 4.                    | 1SET     | BONNET INSULATOR CLIP <i>11</i>                   |            | 50.00      |
| 5.                    | 1SET     | FRONT FENDER INNER SHIELD CLIP <i>11</i>          |            | 90.00      |

CONTINUE / ...

*12051.1*  
*252*  
*9038.32*


## FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk 1 / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg

**FALCON-AIR**

MS FIRST CAPITAL INSURANCE LIMITED  
36 ROBINSON ROAD  
#16-01 CITY HOUSE SINGAPORE 068877

Attention : Motor Claim Department

Contact : 62222311 Fax No. : 62223547

**Estimate : ES707788**

Date : 24/11/2020

Vehicle Num. : SJY 5169P

Make/Model : TOYOTA PRIUS

Chassis/Eng# : ZVW305123371

Accident Date : 23/11/2020

Claim No. :

Reference :

Policy No. :

| S/N | Quantity | Particular | Unit Price | Amount S\$ |
|-----|----------|------------|------------|------------|
|-----|----------|------------|------------|------------|

|    |      |                                      |       |       |
|----|------|--------------------------------------|-------|-------|
| 6. | 1SET | RADIATOR SUPPORT TOP GARNISH CLIP    |       | 50.00 |
| 7. | 2PCS | RADIATOR SUPPORT TOP GARNISH STICKER | 40.00 | 80.00 |
| 8. | 2PCS | HORN BRACKET                         | 40.00 | 80.00 |
| 9. | 1BTL | COOLANT                              |       | 30.00 |

Special Nett Total S\$ :

645.00

LABOUR :

TO CHECK LIGHT SYSTEM AND WIRING

ANTI-RUST

TO APPLY BODY SEALANT ON BODY JOINTS

TO VACCUM, REOIL AND REGAS AIR CON

TO RNR HYBRID SYSTEM

TO PLUG IN DIAGNOSTIC AND REPROGRAM HYBRID SYSTEM

LABOUR/PANEL BEATING

TO PUTTY AND RESPRAY ACCIDENT DAMAGED PARTS

Labour Total S\$ :

3,160.00

E. &amp; O.E.

Total S\$ :

20,112.19

for FALCON AIR AUTO SERVICES PTE LTD

TAMPINES BRANCH

**FALCON-AIR AUTO SERVICES PTE LTD**

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk 1 / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg