

Not Authored
Penny B4 paint

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB7919Z

AAD2011-130

8 6959.80

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

25 NOV 2020

SHB7919Z

JTDKB3FU003083328

TOYOTA

PRIUS

24/11/2020

ERGO

30/08/2019

PART

- 1 COVER, FRONT BUMPER
- 1 RETAINER, REAR BUMPER SIDE, LH
- 1 UNIT, HEADLAMP, LH
- 1 COMPUTER SUB-ASSY, HEADLAMP, LH NO.1
- 1 LAMP ASSY, FOG, LH
- 1 PANEL SUB-ASSY, FRONT DOOR, LH
- 1 WEATHERSTRIP, FRONT DOOR, LH
- 1 HINGE ASSY, FRONT DOOR, LOWER LH
- 1 HINGE ASSY, FRONT DOOR, UPPER LH
- 1 TAPE, BLACK OUT, NO.1 FRT LH
- 1 TAPE, BLACK OUT, NO.2 FRT LH
- 1 TAPE, BLACK OUT, NO.3 FRT LH
- 1 MOTOR ASSY, POWER WINDOW REGULATOR, FRT LH
- 1 REGULATOR SUB-ASSY, FRONT DOOR WINDOW, LH
- 1 MOULDING, FRONT DOOR WINDOW FRAME, FRONT LH
- 1 WEATHERSTRIP, FRONT DOOR FIX WINDOW, LH
- 1 FENDER SUB-ASSY, FRONT LH
- 1 EMBLEM, SIDE PANEL
- 1 LINER, FRONT FENDER, LH
- 1 MIRROR ASSY, OUTER REAR VIEW, LH
- 1 COVER SUB-ASSY, FRONT PILLAR, UPR LH
- 1 MOULDING, WINDSHIELD, OUTSIDE LH
- 1 MOULDING ASSY, BODY ROCKER PANEL, LH
- 1 REINFORCE SUB-ASSY, ROCKER, OUTER LH
- 1 REINFORCEMENT SUB-ASSY, ROCKER PANEL, LH

LIST

\$	CM	516.00	✓
\$	DI	116.50	✓
\$	MS	1,781.10	✓
\$	SL	960.50	X
\$	SL	951.40	X
\$	R	1,300.70	✓
\$	SL	231.30	X
\$	R	110.60	X
\$	R	97.50	X
\$	ME	13.30	✓
\$	ME	43.50	✓
\$	ME	26.30	✓
\$	SL	926.00	X
\$	SL	238.30	X
\$	SL	38.60	X
\$	SL	76.40	X
\$	R	977.80	✓
\$	ME	54.60	✓
\$	CM	202.50	✓
\$	CM	1,339.30	✓
\$	SL	100.40	X
\$	SL	85.50	X
\$	BU	594.80	✓
\$	R	583.40	X
\$	R	343.40	X

TOTAL \$ 11,709.70